

Willamina High School

Willamina SD 30J

Yamh_sch09A

Building Type School	County Yamhill	
Street 1100 Oaken Hills Dr		
City Willamina	State OR	Zip 97396
Latitude 45.08556	Longitude 123.47527	
Tracking Code RVS in 2006	Inspection Date 8/10/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Willamina High School

Final RVS Score

Final Type	Final Score
RM1	1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Willamina High School

Yamh_sch09A

Enrollment 340	Year Built (Field Verified) 1981	Year Built (Alt. Source) 1980	Est. Decade Built 1980
Total Area (square ft) 45000	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes	
Reentrant Corners: Other (Adjacent Build/Entity)		Building On Hill or Sloped Site	
None		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
Falling Hazards		Poor Conditions	
Other: General		None	
None		None	
None		None	
			
NE General Site		NE Vertical Irregularity Secondary	
		S Elevation View	
			
NE Primary Structural Type		NE Vertical Irregularity Secondary	
		N Vertical Irregularity Primary	
			
W General Site		W Elevation View	
		W Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Willamina High School

Yamh_sch09A



S Elevation View



E Elevation View



SE Field Verified Year Built
1981

Willamina High School

Willamina SD 30J

Yamh_sch09B

Building Type School	County Yamhill	
Street 1100 Oaken Hills Dr		
City Willamina	State OR	Zip 97396
Latitude 45.08526	Longitude 123.47583	
Tracking Code RVS in 2006	Inspection Date 8/10/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Willamina High School

Final RVS Score

Final Type	Final Score
RM1	1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Willamina High School

Yamh_sch09B

Enrollment 340	Year Built (Field Verified) 1980	Year Built (Alt. Source) 1980	Est. Decade Built 1980
Total Area (square ft) 45000	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
Reentrant Corners: L Shaped (Adjacent Build/Entity)		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None			
 SE Elevation View		 S Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries