

# Patton Middle School

McMinnville SD 40

Yamh\_sch14A

Building Type	County
School	Yamhill
Street	
1175 E 19th St	
City	State Zip
McMinnville	OR 97128
Latitude	Longitude
45.22258	123.18618
Tracking Code	Inspection Date
RVS in 2006	8/15/2006



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Tertiary		0	0	0	0	0	0	0	0	0


Patton Middle School

## Final RVS Score

Final Type	Final Score
C2	0.7

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

# Patton Middle School

Yamh\_sch14A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
768	1977	1977	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
136600	1	No	Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
Reentrant Corners: Other (Adjacent Build/Entity)		None	
None		None	
Falling Hazards		Poor Conditions	
Other: Brick Veneer		None	
Other: General		None	
None		None	
			
SW General Site	NW General Site	NW Pounding Potential	
			
S Falling Hazard	W Falling Hazard	N Elevation View	
			
NE Elevation View	N Falling Hazard Wall disconnected at gap.	N Plan Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Patton Middle School

Yamh\_sch14A



NE Elevation View  
Wall around mech/loading dock area.



N Elevation View



NW Elevation View  
locker room on bldg C same type as bldg A



NW Plan Irregularity Secondary



N Primary Structural Type  
Possible cavity wall, behind first layer of brick some concrete  
can be seen inside the hole



SW Vertical Irregularity Primary



SE Elevation View



SW Plan Irregularity Primary



E Elevation View



SE Plan Irregularity Primary



S Falling Hazard



# OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Patton Middle School

McMinnville SD 40

Yamh\_sch14B

Building Type	County
School	Yamhill
Street	
1175 E 19th St	
City	State Zip
McMinnville	OR 97128
Latitude	Longitude
45.22258	123.18689
Tracking Code	Inspection Date
RVS in 2006	8/15/2006



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Tertiary		0	0	0	0	0	0	0	0	0


Patton Middle School

## Final RVS Score

Final Type	Final Score
C2	0.7

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

# Patton Middle School

Yamh\_sch14B

Enrollment 768	Year Built (Field Verified) 1977	Year Built (Alt. Source) 1977	Est. Decade Built 1970
Total Area (square ft) 136600	Number of Stories 2	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: T shaped		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Reentrant Corners: T shaped (Adjacent Build/Entity)		None	
None		None	
Falling Hazards		Poor Conditions	
Other: General		None	
Other: Brick Veneer		None	
None		None	
			
S Elevation View	SW Elevation View	SW Pounding Potential	
			
NW Elevation View	N Elevation View	NE Elevation View	
			
N Plan Irregularity Secondary			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Patton Middle School

McMinnville SD 40

Yamh\_sch14C

Building Type	County
School	Yamhill
Street	
1175 E 19th St	
City	State Zip
McMinnville	OR 97128
Latitude	Longitude
45.22233	123.18511
Tracking Code	Inspection Date
RVS in 2006	8/15/2006



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	PC1	2.6	0	-0.5	0	0	0	-0.6	0	1.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Patton Middle School

## Final RVS Score

Final Type	Final Score
PC1	1.5

## FEMA-154 Collapse Potential


Moderate (>1%)



OregonGeology

# Patton Middle School

Yamh\_sch14C

Enrollment 768	Year Built (Field Verified) 1977	Year Built (Alt. Source) 1977	Est. Decade Built 1970
Total Area (square ft) 136600	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	
 NW Primary Structural Type Caulked edge. Picture is of corner of bldg.		 NE Elevation View	 SE Elevation View
 SW Vertical Irregularity Primary			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries