

# Dayton Jr High School

Dayton SD 8

Yamh\_sch19A

Building Type	County
School	Yamhill
Street	
801 Ferry St	
City	State Zip
Dayton	OR 97114
Latitude	Longitude
45.21575	123.08541
Tracking Code	Inspection Date
RVS in 2006	8/9/2006



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	0	-0.6	0	2.2
Secondary	W2	3.8	0	0	0	0	0	-0.8	0	3
Tertiary		0	0	0	0	0	0	0	0	0

Dayton Jr High School

### Final RVS Score

Final Type	Final Score
RM1	2.2

### FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# Dayton Jr High School

Yamh\_sch19A

Enrollment 258	Year Built (Field Verified) 1969	Year Built (Alt. Source) 1969	Est. Decade Built 1960
Total Area (square ft) 35613	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards Other: Brick Veneer		Poor Conditions None None None	
 E Elevation View		 S General Site	
 SW Elevation View		 W Elevation View	

# Dayton Jr High School

Dayton SD 8

Building Type	County
School	Yamhill
Street	
801 Ferry St	
City	State Zip
Dayton	OR 97114
Latitude	Longitude
45.21603	123.08549
Tracking Code	Inspection Date
RVS in 2006	8/9/2006



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	0	-0.6	0	2.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Dayton Jr High School

### Final RVS Score

Final Type	Final Score
RM1	2.2

### FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# Dayton Jr High School

Yamh\_sch19B

Enrollment 258	Year Built (Field Verified) 1969	Year Built (Alt. Source) 1969	Est. Decade Built 1960
Total Area (square ft) 35613	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards Other: Brick Veneer		Poor Conditions None None None	
 E Elevation View		 NE Pounding Potential walkway connects both bldgs	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries