

Dayton Grade School

Dayton SD 8

Yamh_sch30A

Building Type	County
School	Yamhill
Street	
526 Ferry St	
City	State Zip
Dayton	OR 97114
Latitude	Longitude
45.21834	123.07837
Tracking Code	Inspection Date
RVS in 2006	8/9/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Dayton Grade School

Final RVS Score

Final Type	Final Score
W2	0.5

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Dayton Grade School

Yamh_sch30A

Enrollment 428	Year Built (Field Verified) 1951	Year Built (Alt. Source) 1951	Est. Decade Built 1950
Total Area (square ft) 50402	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: U shaped		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Reentrant Corners: L Shaped (Adjacent Build/Entity)		None	
None		None	
Falling Hazards		Poor Conditions	
Other: Brick Veneer		Visible Dry Rot	
None		None	
None		None	
			
W Primary Structural Type	W Elevation View	W Field Verified Year Built 1951	
			
SE Elevation View	SE Elevation View	S Elevation View	
			
SW Plan Irregularity Primary	E Poor Condition	W Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Dayton Grade School

Yamh_sch30A



NE Elevation View



NW Elevation View



NE Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries