

Amity Middle School

Amity SD 4J

Yamh_sch32A

| | |
|---------------|-----------------|
| Building Type | County |
| School | Yamhill |
| Street | |
| 115 Church St | |
| City | State Zip |
| Amity | OR 97101 |
| Latitude | Longitude |
| 45.11365 | 123.20513 |
| Tracking Code | Inspection Date |
| RVS in 2006 | 8/14/2006 |



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | W2 | 3.8 | -2 | -0.5 | -1 | 0 | 0 | -0.8 | 0 | -0.5 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Amity Middle School

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| W2 | -0.5 |

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Amity Middle School

Yamh_sch32A

| | | | |
|--|-------------------------------------|--|---------------------------|
| Enrollment 198 | Year Built (Field Verified) 1935 | Year Built (Alt. Source) 1935 | Est. Decade Built 1930 |
| Total Area (square ft) 30468 | Number of Stories 1 | Basement | Pounding Potential Yes |
| Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) Reentrant Corners: L Shaped None | | Vertical Irregularities Steps in Elevation View: Single Change None None | |
| Falling Hazards Other: Brick Veneer None None | | Poor Conditions None None None | |
|  N Elevation View | |  NW Other | |
|  NW Primary Structural Type | |  NE Elevation View | |
|  E Basement | |  E Plan Irregularity Primary | |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Amity Middle School

Amity SD 4J

Yamh_sch32B

| | | |
|------------------------------|------------------------------|--------------|
| Building Type School | County Yamhill | |
| Street 115 Church St | | |
| City Amity | State OR | Zip 97101 |
| Latitude 45.11351 | Longitude 123.20531 | |
| Tracking Code RVS in 2006 | Inspection Date 8/14/2006 | |



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | W2 | 3.8 | -2 | -0.5 | -1 | 0 | 0 | -0.8 | 0 | -0.5 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Amity Middle School

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| W2 | -0.5 |

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Amity Middle School

Yamh_sch32B

| | | | |
|--|--|--|---------------------------|
| Enrollment 198 | Year Built (Field Verified) 1935 | Year Built (Alt. Source) 1935 | Est. Decade Built 1930 |
| Total Area (square ft) 30468 | Number of Stories 1 | Basement | Pounding Potential Yes |
| Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None | | Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None | |
| Falling Hazards Unreinforced Chimneys Other: General None | | Poor Conditions None None None | |
|  |  |  | |
| SW Elevation View | S Falling Hazard | SW Falling Hazard | |
|  |  | | |
| NW Elevation View | NW Other | | |

Amity Middle School

Amity SD 4J

Yamh_sch32C

| | |
|---------------|-----------------|
| Building Type | County |
| School | Yamhill |
| Street | |
| 115 Church St | |
| City | State Zip |
| Amity | OR 97101 |
| Latitude | Longitude |
| 45.1133 | 123.20514 |
| Tracking Code | Inspection Date |
| RVS in 2006 | 8/14/2006 |



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | W2 | 3.8 | -2 | -0.5 | 0 | 0 | 0 | -0.8 | 0 | 0.5 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Amity Middle School

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| W2 | 0.5 |

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Amity Middle School

Yamh_sch32C

| | | | |
|---|-------------------------------------|---|---------------------------|
| Enrollment 198 | Year Built (Field Verified) 1953 | Year Built (Alt. Source) 1935 | Est. Decade Built 1950 |
| Total Area (square ft) 30468 | Number of Stories 1 | Basement | Pounding Potential Yes |
| Plan Irregularities | | Vertical Irregularities | |
| Reentrant Corners: Other | | Steps in Elevation View: 2 to 3 Changes | |
| Reentrant Corners: Other (Adjacent Build/Entity) | | None | |
| None | | None | |
| Falling Hazards | | Poor Conditions | |
| Other: General | | None | |
| None | | None | |
| None | | None | |
|  | |  | |
| S Vertical Irregularity Primary | SE Elevation View | SW Elevation View | |
|  | |  | |
| NW Plan Irregularity Primary | SW Elevation View | NW Falling Hazard | |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries