#### **OREGON STATE HISTORIC PRESERVATION OFFICE**

Certified Local Government Grant Project Packet Cover Form

| SECTIO        | N I. PROPERTY &    | GRANT INFOR     | MATION                  |                         |   |
|---------------|--------------------|-----------------|-------------------------|-------------------------|---|
| Pro           | operty Address:    | _114 N Main S   | t                       |                         |   |
|               | City:              | Jefferson       |                         |                         |   |
|               | County:            | Marion          |                         |                         |   |
|               | Owner:             | City of Jeffers | on                      |                         |   |
| Owner         | Contact Name:      | Sarah Cook, (   | City Manager/Record     | der                     |   |
|               | Owner Phone:       | 541.327.2768    | 8 Ext. 304              |                         |   |
|               | Owner Email:       | Jeffersonreco   | rder@peak.org           |                         |   |
| (             | Owner Address:     | PO Box 83, Je   | fferson, OR 97352       |                         |   |
| SHPO A        | greement Numb      | er:OR .         | _2112                   | Grant                   | Award Amount: \$10,000  |
| SECTIO        | N II. PROJECT DE   | SCRIPTION       |                         |                         |   |
|               |                    |                 | ed work identifying iss | ues beina addressea     | and how. Attach additional pages if necessary.  |
|               |                    |                 |                         |                         | will be altered, removed, or replaced. This section                                       |
|               |                    |                 | "before and after" un   | derstanding of the p    | project; how the building looks now versus how it   |
|               | once the project i |                 |                         |                         |   |
| _             | , -                | •               | • •                     |                         | the first floor exterior of the Jacob Conser  |
|               | •                  | _               |                         | •                       | insulating factor for the new museum to be  |
|               |                    |                 | •                       | •                       | d Millwork of Eugene, OR. Since most of the Douglas Fir frames that will allow the frames |
|               |                    |                 |                         |                         | e original material in the house. The four  |
|               |                    |                 | •                       | <del>-</del>            | rs were sent to the company and CAD   |
|               |                    | •               | ·                       |                         | I correctly and bring a consistent design to the  |
| -             | =                  | •               | _                       |                         | Ill be repurposed inside the building for the   |
| •             |                    |                 |                         | _                       | from Antique Hardware in Portland in a  |
|               |                    |                 |                         |                         | xtra security." Updated description on  |
|               | d pages.           |                 |                         | •                       | , ,   |
| <b>SECTIO</b> | N IIA. PROJECT I   | DETAIL - SELECT | ALL THAT APPLY          |                         |   |
|               | Roof               | Construct       | ion Date:               | <b>Existing Materia</b> | l:  |
|               | ☐ Repair ☐         | Replace         | Proposed Material       | s:                      |   |
| $\boxtimes$   | Windows/Doors      | s Construct     | ion Date: 1854          | <b>Existing Materia</b> | l: Douglas Fir  |
|               | ☐ Repair 区         | Replace         | Proposed Material       | s: Douglas Fir          |   |
|               | Structural or      | Construct       | ion Date                | Existing Materia        | ŀ   |
|               | Foundation         |                 |                         | _                       |   |
|               | ☐ Repair ☐         | [               | Proposed Material       |                         |   |
|               | Siding             | Construct       |                         | Existing Materia        | I.  |
| _             | ☐ Repair ☐         | - ·             | Proposed Material       |                         |   |
|               | Façade/Entrywa     | ay Construct    | ion Date:               | Existing Materia        | l:  |
|               | ☐ Repair ☐         | Replace         | Proposed Materia        |                         |   |
|               | Other:             |                 | Construction [          | late                    | cisting<br>laterial:  |
|               | ☐ Repair [         | Replace         | Proposed Material       | s:                      |   |

☐ Ground will be disturbed.

Describe:

| Please merge & attach ite | ms as one document and use the file name format "yourprojectaddress.pdf". Check the appropriate boxes formation has been included. Only the map and photographs of property are required.     |  |  |  |  |
|---------------------------|---|--|--|--|--|
|                           | Photographs   |  |  |  |  |
|                           | ☑ At least 2 photographs that provide an overview of the exterior of the property   |  |  |  |  |
|                           | ☑ At least 2 close-ups of the part(s) of the property where the project will happen   |  |  |  |  |
|                           | ☑ At least 2 photographs that provide a view of the property with neighboring properties.   |  |  |  |  |
|                           | Мар   |  |  |  |  |
|                           | Please include a topographic, Google, or Bing map that clearly shows the location of the property.  |  |  |  |  |
|                           | Additional Information  |  |  |  |  |
|                           | ☐ Design plans  |  |  |  |  |
|                           | ☐ Product/material information sheets   |  |  |  |  |
|                           | ☐ Examples of similar completed projects  |  |  |  |  |
|                           | ☐ Other:  |  |  |  |  |
| Section IV. FOR SHPO      | COMPLETION  |  |  |  |  |
|                           | on submitted to our office, we find that the proposed project adheres to <i>The Secretary of the</i>  |  |  |  |  |
| regarding this finding, t | the Treatment of Historic Properties. Pending concurrence from the National Park Service (NPS) this project is fundable through a Certified Local Government Grant for development. Within 30 |  |  |  |  |
| days of the signature b   | elow, please upload your Preservation Agreement to OPRD Grants Online. Work on your project   |  |  |  |  |

cannot begin until a Preservation Agreement has been signed and the project has been submitted to and approved by the

9/29/2021

Date

CECTION III. A DOITION AL INICODA ATTACHA ENTE

NPS.

Joy Sears
SHPO Reviewer Signature

# Progress Report on CLG 2021 Grant for Jacob Conser House in Jefferson, Oregon.


This Progress Report is directed at the four exterior doors portion of the storm windows/doors CLG grant of the Conser House. Three half light doors are located on the East side of House, and a fourth vandalized door is located on the West side of the Event room.



## Vandalized solid back door:

Although painted gray at this point, this door is not functional because the area around the lockset has been gouged and that panel has been compromised. In addition, the hinges are on the outside.

This bottom left picture shows the new color on the back door and the location of the hinges on the outside. Through research, it was discovered that the bathroom door was an original exterior door. When the back "lean to" addition was removed, this door moved to the interior. This white door in the lower right photo is going to be stripped and refinished as much as possible to resemble the faux painting that was done in 1940 in the Event room. The cost of this refinishing is being covered by the last of a Kinsman Grant.





### **East Side Doors:**





These two doors will be replaced. The door to the Event room (left picture) also has hinges on the exterior and multiple areas where locks have been added and moved. The library dropbox door will also be replaced. Both doors will have their hinges on the interior for security of the building. The third door, (not shown) is another 1939 original door on the new Museum side. It will remain and not be replaced.

The Event Room door design also was present in 1939, so the work that will be done with the replacement doors will mimic this design with three horizontal panels. Mid-Valley Glass and Millwork will adjust their contract to mimic the dimensions exactly of the Event room door.

A new "traditional" style door will be purchased to replace the bathroom door.

# The new Door budget is as follows:

| Item   | Cost            | Total     |
|--|-----------------|-----------|
| Two Half Light Doors will mimic Event room door & be made of Douglas Fir   | \$1394.77<br>ea | \$2789.54 |
| Preparation work: Paint 2 doors, remove old doors, make changes to door jambs as needed to accommodate interior swing, | \$200.00 ea     | \$400.00  |
| Preparation work for back door as needed   | \$200.00        | \$200.00  |
| Purchase historic door hardware that includes a deadbolt for security. (Antique Hardware - Portland Oregon)            | \$275.00        | \$1100.00 |
| Purchase traditional style bathroom replacement door (to be painted)   |                 | \$815.00  |
| City Staff time - reports, management, labor   |                 | \$250.00  |
| Volunteer time to coordinate activities  |                 | \$120.00  |
| Door Project Total   |                 | \$5674.54 |







Q

#### bing maps

128 N Main St, Jefferson, OR 97352

Location: 44.71764, -123.0121058

Jacob Conser House historic address is 114 N Main St.

