

# Oregon Seismic Status Report - 2019



*Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.*

*This report was generated by DOGAMI from submitted data.*

**School District/ESD:** Hillsboro 1J

County: WASHINGTON

Contact Name: Casey Waletich

Contact Email: waleticc@hsd.k12.or.us

**Structures Replaced?** Yes

Name and Address: Eastwood ES, 2100 NE Lincoln St., Hillsboro, OR 97124

Kind of Structure: Exterior portable classrooms

Type of Replacement: Wood frame modular building

Max Occupancy: 75

Date Occupied: 09/03/19

**Structures Modified?** Yes

Name and Address: Eastwood ES, 2100 NE Lincoln St., Hillsboro, OR 97124

Kind of Structure: Undercover play structure

Type of Modification: Added engineered bolted plates to adequately transfer sheer load to the sheer walls

Date Re-occupied: 09/03/19

**Optional:**


Engineering Report?  *If yes, attachments are appended to this report.*

Cost of Rehab:

Method of Funding:

Notes:

# Oregon Seismic Status Report - 2019



**Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.**

**This report was generated by DOGAMI from submitted data.**

**School District/ESD:** Hillsboro 1J

County: WASHINGTON

Contact Name: Casey Waletich

Contact Email: waleticc@hsd.k12.or.us

**Structures Replaced?** Yes

Name and Address:

Kind of Structure:

Type of  
Replacement:

Max Occupancy:

Date Occupied:

**Structures Modified?** Yes

Name and Address: Evergreen MS, 550 NW Evergreen R.d., Hillsboro, OR 97124

Kind of Structure: Main Building

Type of Modification: Structural blocking attaching exterior walls to the roof and shear walls throughout interior

Date Re-occupied: 08/28/19

**Optional:**


Engineering Report?  *If yes, attachments are appended to this report.*

Cost of Rehab:

Method of Funding:

Notes:

# Oregon Seismic Status Report - 2019



*Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.*

*This report was generated by DOGAMI from submitted data.*

**School District/ESD:** Hillsboro 1J

County: WASHINGTON

Contact Name: Casey Waletich

Contact Email: waleticc@hsd.k12.or.us

**Structures Replaced?** Yes

Name and Address:

Kind of Structure:

Type of  
Replacement:

Max Occupancy:

Date Occupied:

**Structures Modified?** Yes

Name and Address: Hillsboro High School, 3285 SE Rood Bridge R.d., Hillsboro, OR 97123

Kind of Structure: Main Building

Type of Modification: New shear walls installed, upgraded roof diaphragms and added roof support for mechanical equipment

Date Re-occupied: 09/03/19

**Optional:**


Engineering Report?  *If yes, attachments are appended to this report.*

Cost of Rehab:

Method of Funding:

Notes:

# Oregon Seismic Status Report - 2019



**Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.**

**This report was generated by DOGAMI from submitted data.**

**School District/ESD:** Hillsboro 1J

County: WASHINGTON

Contact Name: Casey Waletich

Contact Email: waleticc@hsd.k12.or.us

**Structures Replaced?** Yes

Name and Address:

Kind of Structure:

Type of  
Replacement:

Max Occupancy:

Date Occupied:

**Structures Modified?** Yes

Name and Address: J.W. Poynter MS, 1535 NE Grant St., Hillsboro, OR 97124

Kind of Structure: Main Building

Type of Modification: Half of the main building was improved with roof strapping tying the roof diaphragm to the interior and exterior walls and shear walls throughout the interior. Other half of building to be complete 13/31/19

Date Re-occupied: 08/28/19

**Optional:**


Engineering Report?  *If yes, attachments are appended to this report.*

Cost of Rehab:

Method of Funding:

Notes:

# Oregon Seismic Status Report - 2019



**Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.  
This report was generated by DOGAMI from submitted data.**

**School District/ESD:** Hillsboro 1J

County: WASHINGTON

Contact Name: Casey Waletich

Contact Email: waleticc@hsd.k12.or.us

**Structures Replaced?** Yes

Name and Address:

Kind of Structure:

Type of  
Replacement:

Max Occupancy:

Date Occupied:

**Structures Modified?** Yes

Name and Address: Lenox ES, 21200 NW Rock Creek Blvd., Portland, OR 97229

Kind of Structure: Main Building

Type of Modification: Seismic hold downs added to the glue lamb beams in the auditorium and in the outdoor play areas along with a strip along the front of the school under the existing siding .

Date Re-occupied: 09/03/19

**Optional:**


Engineering Report?  *If yes, attachments are appended to this report.*

Cost of Rehab:

Method of Funding:

Notes:

## Oregon Seismic Status Report - 2019



**Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.**

**This report was generated by DOGAMI from submitted data.**

**School District/ESD:** Hillsboro 1J

County: WASHINGTON

Contact Name: Casey Waletich

Contact Email: waleticc@hsd.k12.or.us

**Structures Replaced?** Yes

Name and Address:

Kind of Structure:

Type of  
Replacement:

Max Occupancy:

Date Occupied:

**Structures Modified?** Yes

Name and Address: Miller Education Center/Miller Big Picture, 440 SE Oak St., Hillsboro, OR 97123

Kind of Structure: Main Building

Type of Modification: Seismically upgrade Classroom Building, Gymnasium, Kitchen and Playshed with new shear walls or brace frames. Removed unreinforced masonry chimney in the boiler room.  
Braced lean-to structure to main building.

Date Re-occupied: 09/03/19

**Optional:**


Engineering Report?  *If yes, attachments are appended to this report.*

Cost of Rehab:

Method of Funding:

Notes:

## Oregon Seismic Status Report - 2019



**Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.**

**This report was generated by DOGAMI from submitted data.**

**School District/ESD:** Hillsboro 1J

County: WASHINGTON

Contact Name: Casey Waletich

Contact Email: waleticc@hsd.k12.or.us

**Structures Replaced?** Yes

Name and Address: Mooberry Elementary, 1230 NE 10th Ave., Hillsboro, OR 97124

Kind of Structure: Exterior portable classrooms

Type of Replacement: Wood frame modular building

Max Occupancy: 130

Date Occupied: 08/26/19

**Structures Modified?** Yes

Name and Address: Mooberry Elementary, 1230 NE 10th Ave., Hillsboro, OR 97124

Kind of Structure: Main building

Type of Modification: Seismic chimney reinforcement

Date Re-occupied: 08/26/19

**Optional:**


Engineering Report?  *If yes, attachments are appended to this report.*

Cost of Rehab:

Method of Funding:

Notes:

# Oregon Seismic Status Report - 2019



**Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.**

**This report was generated by DOGAMI from submitted data.**

**School District/ESD:** Hillsboro 1J

County: WASHINGTON

Contact Name: Casey Waletich

Contact Email: waleticc@hsd.k12.or.us

**Structures Replaced?** Yes

Name and Address:

Kind of Structure:

Type of  
Replacement:

Max Occupancy:

Date Occupied:

**Structures Modified?** Yes

Name and Address: R.A. Brown Middle School, 1505 SE Cornelius Pass Rd., Hillsboro, OR 97123

Kind of Structure: Main Building

Type of Modification: Seismic bracing added on all glue lamb beams that run through the old wood shop , IT room and numerous other places in the main school , the Gym had a band of steel bolted around the perimeter of upper and lower gyms ,the exterior of the building had over 700 bolts drilled into the concrete and epoxied in around the top of the gym, and seismic strapping was added in strategic places under the entire roof before installing the new roofing

Date Re-occupied: 09/03/19

**Optional:**

Engineering Report?  *If yes, attachments are appended to this report.*

Cost of Rehab:

Method of Funding:

Notes:



# Oregon Seismic Status Report - 2019



*Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.*

*This report was generated by DOGAMI from submitted data.*

**School District/ESD:** Hillsboro 1J

County: WASHINGTON

Contact Name: Casey Waletich

Contact Email: waleticc@hsd.k12.or.us

**Structures Replaced?** Yes

Name and Address:

Kind of Structure:

Type of  
Replacement:

Max Occupancy:

Date Occupied:

**Structures Modified?** Yes

Name and Address: West Union, 23870 NW West Union R.d., Hillsboro, OR 97124

Kind of Structure: Main Building

Type of Modification: Seismic structural columns (structural reinforcement)

Date Re-occupied: 08/26/19

**Optional:**

Engineering Report?  *If yes, attachments are appended to this report.*

Cost of Rehab:

Method of Funding:

Notes: