Monterey Drystack Retaining Wall Treatment

ABOVE: An artist's interpretation of the project with Monterey Drystack Wall Treatment and project landscaping following I-5 Iowa Viaduct construction. Tree and plant species are representative-only of what will be planted.

INFORMATION ONLY

"This product is for informational purposes and may not have been prepared for or be suitable for legal, engineering, or surveying purposes. Users of this information should review or consult the primary data and information sources to ascertain the usability of the information."

AT RIGHT: An enlarged sample of the Monterey Drystack Wall Treatment.



I-5: Iowa Street
Viaduct Replacement Project

Prepared by Darla S. Cole-Bowen, Engineering Illustrator, Graphic Design Specialist
This display for information purposes only. Information provided here is subject to change without notice. Contact source to verify.
ODOT Region 1 Community Affairs Department, 123 NW Flanders Portland, Or 97209 (503) 731-8483 Completed 4/19/2011

Oregon Department of Transportation