SW TUALATIN VALLEY HIGHWAY AT 185TH AVENUE
INTERSECTION IMPROVEMENTS

WHAT'S THE PROBLEM ?

2009-2013 COLLISION HISTORY

156 TOTAL COLLISIONS
- 55% INJURIES & 0 FATALITIES
- 55% CRASHES 12PM - 6PM

PREDOMINANT COLLISION TYPES

LEFT-TURN EXITING DRIVEWAYS + STREETS
LEFT-TURN ENTERING DRIVEWAYS + STREETS
REAR-END COLLISIONS
COLLISIONS WITH PEDESTRIANS

PROPOSED SOLUTIONS

PROVIDE FOR U-TURNS AT 185TH AVE
- Provides driveway access

INSTALL RAISED TRAFFIC SEPARATOR
- Eliminates left-turn collisions

INSTALL SUPPLEMENTAL SIGNAL HEADS TO IMPROVE SIGNAL VISIBILITY
- Reduces rear-end collisions

RELOCATE BUS SHELTER
- Improves traffic flow
- Improves pedestrian visibility

ILLUMINATION
- Improves visibility

ISLAND/SLIP LANE REMOVAL

FOR INFORMATIONAL PURPOSES ONLY
SUBJECT TO CHANGE

Oregon Department of Transportation

QUESTIONS OR COMMENTS?

E-mail: Lili.D.Boicourt@odot.state.or.us
Website: www.oregon.gov/ODOT/HWY/REGION1/Pages/TV185th.aspx
Phone: (503) 731-8247 - Lili Boicourt, ODOT Region 1 Community Affairs

NOT TO SCALE
JANUARY 2015
NORTH