HISTORY OF OIL OR GAS WELL

(In compliance with rules and regulations pursuant to ORS 520)

CAV

D Y OIL, INC.
(Company or operator)

ARCO
(Lease)

FOREST 13-6
(Well No.)

Sec. SW ¼ 6 , T. 5N , R. 5W W.B.&M. Surveyed Coordinates: Surface –

2368.25' N and 689.02' E from SW corner sec 6

Wildcat: _____ (or) Field Name: Mist

County: Columbia

Signature: _____

Date: 08-19-89

Position: Agent

Use this form in reporting the daily operations at the well. (Operator may use his own forms, but heading of this form must also be completed and submitted.) Please submit a complete history of the well. Include such information as bit sizes, mud weights, casing sizes and depths set, amount of cement used, drilling depths, fishing, logging, perforating, and plugging procedures, and anything else pertinent to the operation. Do not include lithology.

Date	
08-08-89	Forest 13-6 (Mist) TD:145' MUD:9.1 VIS:38 Spud well at 3:00pm. Drilled 12¼" to 145'
08-09-89	Forest 13-6 (Mist) TD:359' MUD:9.1 VIS:43 Circ clean hole, short trip. Trip out for casing. Run 8 5/8" casing to 359'. Cemented to surface w/200 sx cement. Cut off conductor. Welded on well head. Tested at 1500 PSI for 15 min, nippled up B.O.P.
08-10-89	Forest 13-6 (Mist) TD:1037.94' MUD:9.0 VIS:40 Test B.O.P. Approved by DOGAMI at 1:10am. Drilled cement out w/7 7/8" out of shoe. Trip out picked up drill collars: circ & survey at 421'. Drilled to 1037.94.
08-11-89	Forest 13-6 (Mist) TD:1611' MUD:9.8-10 VIS:46 Trip and ream as needed. Repair rig and service. Wipe hole – tight from 1426' to 900'. Circ bottoms up and drilled. 29½ hours on bit.
08-12-89	Forest 13-6 (Mist) TD:1796' MUD:10.2 VIS:47 Drilled to TD 1796'. Made wiper trip to shoe. Circ hole clean. Drop survey – 1796' 24° 582E. Ran E logs. R.I.H. w/DCS. Break kelly and L.D.D.C.S. and direc- tional. Set cement plug – 42sx 2% CAC/2. Tag at 304'-409'. CIP at 8:05am. W.O.C. Clean mud pits. Rig down. Top plug 0-20'. Plugs witnessed & approved by DOGAMI. Cut off casing head. Weld on cap.