Form 4 1/54

STATE OF OREGON
DEPARTMENT OF GEOLOGY AND MINERAL INDUSTRIES
1069 State Office Building,   Portland 1, Oregon

WELL SUMMARY REPORT
(Submit in duplicate)

Operator __W.F. Kemin_____ Field _____ __Dillard Area__ _____

Well No. __D. Coon 1____ SE 1/4 Sec. _30__ , T _28S_ , R __6W_ , _____ __WM_____ W. B. & M.

Location _____ Elevation above sea level _____ __940'__ _____ feet

All depth measurements taken from top of_____ , which is _____ feet above ground

In compliance with the rules and regulations pursuant to ORS 520 (Chapter 667 OL 1953) the information given herewith is a complete and correct record of the present condition of the well and all work done thereon, so far as can be determined from all available records.

Date _____ __1950__ _____   Signed _____ __W.L. Kemin__ _____

                                                 Title _____ __Operator__ _____
___Engineer or Geologist_____ ___Superintendent_____   (President, Secretary or Agent)

Commenced drilling_____ Completed drilling_____ Drilling tools Cable / Rotary

Total depth __150'_____ Plugged depth _____ 0 _____   GEOLOGICAL MARKERS   DEPTH

Junk_____   __Dothan Fm.__ _____   __0-150'__

Commenced producing_____ Flowing/gas lift/pumping
                              Date   (cross out unnecessary words)

	Clean oil bbl. per day	Gravity Clean oil	Percent water including emulsion	Gas Mcf. per day	Tubing Pressure	Casing Pressure
Initial production						
Production after 30 days						

CASING RECORD (Present Hole)

Size of casing (A.P.L)	Depth of shoe	Top of casing	Weight of casing	New or second hand	Seamless or Lapweld	Grade of casing	Size of hole drilled	No. of sacks of cement	Depth of cementing if through perforations
12"	40'+	(min. .025 wall)					14"	--	

PERFORATIONS

Size of casing	From	To	Size of perforations	Number of rows	Distance between centers	Method of perforations
	ft.	ft.				
	ft.	ft.				
	ft.	ft.				
	ft.	ft.				
	ft.	ft.				

Electrical Log Depths _____ _____ (Attach Copy of Log)