## **Biglow Canyon Wind Farm**

## DEQ Report of Incidents from 11/2/2007 to 11/3/2021

			Quantity	Unit of	Media		
Description of Release	Release Date	Material	Released	Measure	Affected	Release Source	RP Organization
PGE reported that 300 gallons of non pcb transformer oil was							_
spilled at the location. No water ways affected. Spill was							
contained to a containment vault, however an unknown							
amount got out of containment. Us Ecology is being contacted							
for clean up.	Mon Jun 14 2021	Oil - Transformer	300	Gallons	Soil	Electrical Equipment	_
Caller reported that 50-100 gallons of non pcb transformer oil							
was spilled at the location. No water ways affected, spill was							
contained to in side the substation on the ground and gravel.							
Spill is contained and clean up crew is being contacted.	Wed Sep 16 2020	Oil - Transformer	100	Gallons	Soil	Business	
Caller reported that 166 gallons of Non PCB Transformer oil was		Oil - Transformer	100	Gallolis	3011	Dusilless	_
released to the ground with transformer failed. No water ways							
affected, and clean up is in process.	Tue May 5 2020	Oil - Transformer	166	Gallons	Soil	Other	_
PGE reported turbine burst at the wind farm causing release of	Tue May 3 2020	Oil - Transionnei	100	Gallolis	3011	Other	_
non PCB mineral oil of up to 400 gallons. No waterways affected							
and oil released onto a gravel pad and dirt where the wind farm							
is located. NRC environmental is being called out to do clean up.							
is located. Whe environmental is being called out to do clean up.	Mon Aug 19 2019	Oil - Transformer	400	Gallons	Soil	Electrical Equipment	_
PGE reports transformer blew at remote site near Wasco,	WOT Aug 15 2015	On Transformer	400	Guilotis	3011	Electrical Equipment	
spilling 600 gallons of transformer oil to ground. NRC							
environmental called for remedial action at the site, oil is newer							
non pcb, location is Big Low Canyon.	Fri Jun 30 2017	Oil - Transformer	600	Gallons	Soil	Electrical Equipment	Portland General Electric
Brandy reported that a turbine #\$ r blewon Saturday. No PCBs.	,,	on manoremen			00	zicotiioai zqaipiiioiit	r ordana conterar zicotino
Unable to perform any clean up (0130) because equipment is							
still energized. Randy Christianson from PGE on-site and will be							
working with SMAF on Monday. The oil is contained in the vault							
under the turbine.	Sat Dec 10 2016	Oil - Transformer	50-480	Gallons	Soil	Farm	Portland General Electric
PGE reporting the spill of 100 gallons transformer oil at the							
Biglow Wind Farm due to a blown hub. The quantity later							
revised to be 600 gallons. SMAF hired to perform cleanup.	Sat Nov 23 2013	Oil - Transformer	600	Gallon	Soil	Electrical Equipment	Portland General Electric
Transformer caught fire releasing oil released to ground surface							
affecting a 100 x 100 foot patch of ground below transformer.	Sun Jun 26 2011	Oil - Transformer	476	Gallons	Soil	Electrical Equipment	_
PGE reporting the spill of 100 gallons mineral oil at 96900							
Heron Rd., Wasco, Oregon. SMAF Environmental has been hired							
to cleanup. The spill was caused by faulty equipment and							
discovered yesterday. The oil is certified non-PCB.	Wed Sep 15 2010	Oil - Transformer	100	Gallons	Soil	Electrical Equipment	-