



IRON WORK:-



- ~~X~~ ~~IRON SCREW PLATES~~ ~~NO 1~~
- 8 ✓ CORNER BRACE " " " 2
- ✓ 2 HOLDING STRAPS " " 3
- ✓ 1 STRAP - EDGE " " 4
- ✓ 4 STRAPS - SIDE " " 5
- 1 HOOK AND EYE BOLT - SET
- 12 LAG SCREWS
- 4 BOLTS $\frac{1}{2}$ " x 4"
- ✓ 3 " $\frac{1}{2}$ " x 38"
- 2 " $\frac{2}{5}$ " x 7"
- ✓ 8 " $\frac{3}{8}$ " x 7"
- 20 " $\frac{1}{2}$ " x 2 $\frac{1}{2}$ "
- 12 " " x 4 $\frac{1}{2}$ "



No 4

BOLT HOLES
1' APART.

No 5



BAK0222