

Instructions: Prepare and submit the "Initial Report" on the first Wednesday after a well is spudded or workover operations are started. Daily work prior to spudding should be summarized on the form giving inclusive dates only.

District	County, parish or borough	State
Western	Columbia	OR
Field	Lease or Unit	Well no.
Mist	Columbia County	4 RD #1
Auth. or W.O. no.	Title	
API #009-00011-01	Plug & Abandon	

Section 15, Township 6 North, Range 5 West (Property Code M830016C6)

Operator	ARCO W.I.
ARCO OIL AND GAS COMPANY	100%
Spudded or W.O. begun	Prior status if a W.O.
Workover	Shut-In

Date and depth as of 8:00 a.m. Complete record for each day reported

11/02/90 (1)
TD: 2894'

4-1/2" @ 2679'
PREP T/P&A, ~~SUEN~~
MIRU. ACCEPT RIG 0700 HRS. WELL DEAD. PMP 6 BBLs LEASE WATER, ESTABLISH RTNS. CIRC 1/2 HR, NO GAS. HELD SAFETY MEETING. SET BPSV, ND TREE, NU BOPE, PULL BPSV. RIH W/TBG, T/CHK PBD @2640 TBG STOPPED 3 JTS IN. MEAS OUT, STOPPED @2340' (REF TO 11'KB) CONTACT DOGAMI. BRIDGE PLUG SET IN 1983 @ 2340'. RIH WITH TBG. HALLIBURTON NOT AVAILABLE TO SET PLUGS UNTIL 11/3/90.

11/03/90 (2)
TD: 2894'

4-1/2" @ 2679'
RELEASED RIG, P&A FINISHED
RU HALLIBURTON. PUMP 230 SX 'G'+3%CACL IN 5 STAGES F/2340' TO SURF. CIP 0855 HRS. RD HALLIB, WASH OUT BOPE & ND. CLEAN MUD PIT & RELEASE RIG @1030 HRS 11/3/90. DAN WERMIEL W/DOGAMI WAIVED WITNESS OF P&A. WELD PLATE ON STUB.

The above is correct

Signature	Date	Title
<i>A. L. Slatts</i>	1/17/91	DISTRICT DRILLING ENGINEER

For form preparation and distribution, see Procedures Manual, Section 10, Drilling, Pages 86 and 87.