STATE OF OREGON DEPARTMENT OF GEOLOGY AND MINERAL INDUSTRIES 1069 State Office Building, Portland 1, Oregon

WELL SUMMARY REPORT (Submit in duplicate)

Operator Willamette Petrol Syndicate						Field Corvallis Area					
	Corvalli									WM.	W. B. & M
Location						_ Elevatio	n above s	sea le	vel22	51+	feet
All depth measurements taken from top of						<u>.</u> .	, , \	which	is		feet above ground
In compliant and correct rords.	te with the rul record of the p	es and re resent co	gulatio idition	ons pursuant of the wel	to OR\$ 52 Il and all w	0 (Chapte ork done t	r 667 OL thereon, s	1953) so far	the informat as can be det	ion given her ermined fron	ewith is a complete r. all available rec-
Date 194!	5					Signed	AAPG	Bull	, v 29 N	o. 10, 19	بل5
						Title			.	-	_
Enginee	r or Geologist		Sup	erintendent			((Presid	ent, Secreta	ry or Agent)	
Commenced	drilling 15	3±			Completed	drilling_	т. А. З. Д.			Drilling to	ols Cable Rotary
Total depth_	21501	Plug	ged de	pth		_	GEOLG	⊃GIC.△	L MARKERS	;	DEPTH
Junk						_Suri	Cicial	Дерс	sits		0 - 35¹
					Oligocene seds (?)					35-6391	
					 	<u>Spend</u>	er Fm.	•		_	639-2150'
										-	
Commenced	producing		De	ate	<u>-</u>	_ Flowing, (cross ou					
		•		lean oil L per day	Gravit Clean c	inch inch	it water iding lsion		Gas f. per day	Tubing Pressure	Casing Pre ss ure
	Initial product	ion									
Production after 30 days							:				
		,									
				CAS	SING RECC	RD (Pres	ent Hole))	1		
Size of casin	Depth of shoe	Top o			New or sec- ond hand				Size of hole drilled	No. of sacks of cement	Depth of cement- ing if through perforations
<u>8"</u>	1560	0	j	?					12"	<u> </u>	
_ •						i					
										<u>. </u>	
						!					i
			<u>.</u>		PERFOR	ATIONS					
		1					Number	Г	istance) (- + b - d	-66
Size of casin	ng From	To		Size	of perfora	tions	of rows	betw	een centers	Method	of perforations
	f	t	ft.						_		
		t	f t.								
		t	ft.					<u> </u>			
		t.	ft.					<u> </u>			-
		t.	ft.		-				\Box		