

## Department of Geology & Mineral Industries

Mineral Land Regulation and Reclamation 229 Broadalbin Street SW Albany, OR 97321-2246 541-967-2039 FAX 541-967-2075

June 20, 2005


Northwest Natural 220 NW 2nd Avenue Portland OR 97209

## Permit to Drill Gas Well

The application to drill a gas well, IW 32DC-10-65, located in Section 10, Township 6N, Range 5W, Columbia County, Mist Storage, DOGAMI ID No. 545, API No. 36-009-00363, has been approved with the following conditions:

## The permittee shall:

1. Construct all sumps/mud pits by excavating below grade with a design and size for holding the drill cuttings and fluid removed from the well. Loose fill material will not be allowed to be used in the construction of the sumps/mud pits for the purposes of water retention.



NO

loose

fill

sump/mud pit excavated below grade

drilling fluids held by loose fill

- 2. Contact DOGAMI two weeks prior to spud.
- 3. Provide DOGAMI with a 2-week, a 3 day, and a 24-hour notice to schedule an inspection to witness all BOPE tests conducted prior to drilling out each casing shoe.
- 4. Per 632-010-0014(C) & (D), the BOPE shall be pressure tested: when installed, prior to drilling out casing shoes, following repairs or reassembly of the preventers that require disconnection a pressure seal in the assembly, and shall be actuated to test proper functioning once each trip or once each week, whichever is more frequent.

Issued on All II, 2003

Bob Houston

Petroleum - Geothermal Geologist

Natural Resource Specialist

Mineral Land Regulation and Reclamation

c: Columbia County