

# Curry General Hospital - Gold Beach

Rural Hospital Operating in Gold Beach

Curr\_hos01A

Building Type	County	
Hospital	Curry	
Street		
94220 Fourth St.		
City	State	Zip
Gold Beach	OR	97444
Latitude	Longitude	
42.41137	124.41853	
Tracking Code	Inspection Date	
RVS in 2006	8/4/2006	



Seismicity Zone: Very High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5
Secondary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Tertiary		0	0	0	0	0	0	0	0	0

Curry General Hospital - Gold Beach

## Final RVS Score

Final Type	Final Score
W2	0.5

## FEMA-154 Collapse Potential

High (>10%)



# Curry General Hospital - Gold Beach

Curr\_hos01A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1951	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	Yes	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
Falling Hazards		Poor Conditions	
Unreinforced Chimneys		None	
None		None	
None		None	



NW General Site



N Vertical Irregularity Primary



W Plan Irregularity Secondary



S Basement



SE Falling Hazard  
Reinforced chimney?



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries