

Mercy Medical Center - Roseburg

Catholic Health Initiatives NFP

Doug_hos03A

Building Type	County	
Hospital	Douglas	
Street		
2700 NW Stewart Pkwy		
City	State	Zip
Roseburg	OR	97470
Latitude	Longitude	
43.24145	123.36707	
Tracking Code	Inspection Date	
New Building	8/25/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary	C1	2.5	-1.5	-0.5	0	0	0	0	0	0.5
Tertiary		0	0	0	0	0	0	0	0	0


Mercy Medical Center - Roseburg

Final RVS Score

Final Type	Final Score
C1	0.5

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Mercy Medical Center - Roseburg

Doug_hos03A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		2006	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
243500	3	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes	
Reentrant Corners: Other (Adjacent Build/Entity)		Steps in Elevation View: Very Irregular Changes (Adjacent Building/Ent)	
None		None	
Falling Hazards		Poor Conditions	
Heavy Cladding (thick stone or concrete)		None	
None		None	
None		None	
			
S Vertical Irregularity Secondary reentrant corners also older portion is at center/top		N General Site construction of newest portion with older hospital in the rear	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries