

Applegate Valley RFPD 9

Jack_fir19A

Applegate Valley RFPD

| | | | |
|-------------------------|-------|-----------------|--|
| Building Type | | County | |
| Fire - RFPD | | Jackson | |
| Street | | | |
| 1095 Upper Applegate Rd | | | |
| City | State | Zip | |
| Jacksonville | OR | 97530 | |
| Latitude | | Longitude | |
| 42.22326 | | 123.04699 | |
| Tracking Code | | Inspection Date | |
| RVS in 2006 | | 7/19/2006 | |



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | W2 | 4.8 | -3 | 0 | 0 | 1.6 | -0.8 | 0 | 0 | 2.6 |
| Secondary | S3 | 3.8 | 0 | 0 | 0 | 0 | -0.6 | 0 | 0 | 3.2 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Applegate Valley RFPD 9

Final RVS Score

Final Type

Final Score

W2

2.6

FEMA-154 Collapse Potential

Low (<1%)




OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

| | | | |
|------------------------|-----------------------------|--------------------------|--------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| | | | 1980 |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| | 2 | No | No |

| | |
|---------------------|---|
| Plan Irregularities | Vertical Irregularities |
| None | Internal Discontinuous Diaphragm (large internal opening) |
| None | None |
| None | None |

| | |
|-----------------|-----------------|
| Falling Hazards | Poor Conditions |
| None | None |
| None | None |
| None | None |



NE Secondary Structural Type
Garage doors on both sides of the building indicate: no torsion problem.



Applegate Valley RFPD 9

Jack_fir19B

Applegate Valley RFPD

| | | | |
|-------------------------|-------|-----------------|--|
| Building Type | | County | |
| Fire - RFPD | | Jackson | |
| Street | | | |
| 1095 Upper Applegate Rd | | | |
| City | State | Zip | |
| Jacksonville | OR | 97530 | |
| Latitude | | Longitude | |
| 42.22306 | | 123.04682 | |
| Tracking Code | | Inspection Date | |
| RVS in 2006 | | 7/19/2006 | |



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | S3 | 3.8 | 0 | 0 | 0 | 0 | -0.6 | 0 | 0 | 3.2 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Applegate Valley RFPD 9

Final RVS Score

Final Type

Final Score

S3

3.2

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

| | | | |
|------------------------|-----------------------------|--------------------------|--------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| | | | 1990 |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| | 1 | No | No |

| | |
|---------------------|-------------------------|
| Plan Irregularities | Vertical Irregularities |
| None | None |
| None | None |
| None | None |

| | |
|-----------------|-----------------|
| Falling Hazards | Poor Conditions |
| None | None |
| None | None |
| None | None |

