

# Lane County Fire District 1

Lane Co Fire Dist #1

Lane\_fir11A

Building Type Fire - RFPD	County Lane	
Street 88794 Fountain Rd		
City Elmira	State OR	Zip 97405
Latitude 44.06773	Longitude 123.35823	
Tracking Code RVS in 2006	Inspection Date 7/24/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary	W1	4.4	-2.5	-0.5	0	0	0	0	0	1.4
Tertiary		0	0	0	0	0	0	0	0	0

Lane County Fire District 1

## Final RVS Score

Final Type	Final Score
RM1	0.7

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Lane County Fire District 1

Lane\_fir11A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No
Plan Irregularities		Vertical Irregularities	
Out of Plane Lateral-Force-Resistance Elements		Steps in Elevation View: Single Change	
Torsion: Eccentric Stiffness		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
W    Vertical Irregularity Primary also shows a plan irregularity, and a solid back wall indicating a possible torsion problem.		NE    Other stairwell to the 2nd floor.	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries