

Colin Kelly Middle School

Eugene SD 4J

Lane_sch12A

Building Type	County	
School	Lane	
Street		
850 Howard Ave		
City	State	Zip
Eugene	OR	97404
Latitude	Longitude	
44.08742	123.14286	
Tracking Code	Inspection Date	
RVS in 2006	1/30/2007	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	0	0	1.3
Secondary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Tertiary		0	0	0	0	0	0	0	0	0

Colin Kelly Middle School

Final RVS Score

Final Type	Final Score
W2	1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Colin Kelly Middle School

Lane_sch12A

Enrollment 522	Year Built (Field Verified) 1945	Year Built (Alt. Source) 1945	Est. Decade Built 1940		
Total Area (square ft) 112356	Number of Stories 1	Basement	Pounding Potential No		
Plan Irregularities		Vertical Irregularities			
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes			
Reentrant Corners: Other (Adjacent Build/Entity)		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)			
None		None			
Falling Hazards		Poor Conditions			
Other: Ornamental Hazard Over Exit		None			
Other: Brick Veneer		None			
None		None			
	N Primary Structural Type		N Falling Hazard		NW Vertical Irregularity Primary
	SW Elevation View		SE Elevation View		S Plan Irregularity Primary
	SW Vertical Irregularity Secondary 1995 gym on rt		N Elevation View b on left		N Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Colin Kelly Middle School

Eugene SD 4J

Lane_sch12B

Building Type	County	
School	Lane	
Street		
850 Howard Ave		
City	State	Zip
Eugene	OR	97404
Latitude	Longitude	
44.08746	123.14144	
Tracking Code	Inspection Date	
RVS in 2006	1/30/2007	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	0	0	2.4	0	0	0	4.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Colin Kelly Middle School

Final RVS Score

Final Type	Final Score
W2	4.2

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Colin Kelly Middle School

Lane_sch12B

Enrollment 522	Year Built (Field Verified) 1945	Year Built (Alt. Source) 1980	Est. Decade Built
Total Area (square ft) 112356	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
Reentrant Corners: Other (Adjacent Build/Entity)		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SE Plan Irregularity Primary		NE Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Colin Kelly Middle School

Eugene SD 4J

Lane_sch12C

Building Type	County	
School	Lane	
Street		
850 Howard Ave		
City	State	Zip
Eugene	OR	97404
Latitude	Longitude	
44.08779	123.14185	
Tracking Code	Inspection Date	
RVS in 2006	1/30/2007	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	-0.5	0	0	0	0	0	3.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Colin Kelly Middle School

Final RVS Score

Final Type	Final Score
W2	3.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Colin Kelly Middle School

Lane_sch12C

Enrollment 522	Year Built (Field Verified) 1945	Year Built (Alt. Source) 1945	Est. Decade Built 1970
Total Area (square ft) 112356	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: L Shaped None None		Vertical Irregularities None None None	
Falling Hazards Other: Brick Veneer None None		Poor Conditions None None None	
 E Primary Structural Type		 NE Elevation View	 SW Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries