

Lebanon Fire District Station 32

Linn_fir02A

Lebanon Fire District

| | | | |
|---------------------|-------|-----------------|--|
| Building Type | | County | |
| Fire - RFPD | | Linn | |
| Street | | | |
| 34128 E Lacombe Rd. | | | |
| City | State | Zip | |
| Lebanon | OR | 97355 | |
| Latitude | | Longitude | |
| 44.58549 | | 122.73899 | |
| Tracking Code | | Inspection Date | |
| RVS in 2006 | | 7/7/2006 | |



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | S3 | 3.8 | 0 | -0.5 | 0 | 0 | -0.6 | 0 | 0 | 2.7 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Lebanon Fire District Station 32

Final RVS Score

Final Type

Final Score

S3

2.7

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

| | | | |
|------------------------|-----------------------------|--------------------------|--------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| | | 1977 | 1980 |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| | 1 | No | No |

| | |
|------------------------------|-------------------------|
| Plan Irregularities | Vertical Irregularities |
| Torsion: Eccentric Stiffness | None |
| None | None |
| None | None |

| | |
|-----------------|-----------------|
| Falling Hazards | Poor Conditions |
| None | None |
| None | None |
| None | None |



N General Site