

Tech Lab Building

Treasure Valley CC

Malh_coc02A

Building Type Community_College	County Malheur	
Street 650 College Blvd		
City Ontario	State OR	Zip 97914
Latitude 44.01917	Longitude 116.97293	
Tracking Code Miller 2004-05	Inspection Date 8/11/2005	

Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Tech Lab Building

Final RVS Score

Final Type	Final Score
RM1	-0.1

FEMA-154 Collapse Potential

Very High (100%)



- 1. Meyer-McLean Theater
TVCC Performing Arts
- 2. Student Services
Four Rivers Cultural Center
Classrooms
- 3. Barber Hall
- 4. Weese Building
- 5. Vo-Tech Building
- 6. CAD & Drafting Classroom
- 7. Tech Lab Building
- 8. Workforce Training Building
- 9. Oregon Trail Building
- 10. Art Building
- 11. Albertson Building
- 12. Maintenance Buildings
- 13. Elks Memorial Baseball Field
- 14. Dr. John J. Easley Memorial
Gymnasium
- 15. Ore-Ida Sports Complex
- 16. Malheur Dormitory
- 17. Owyhee Dormitory
Student Life Office

Tech Lab Building

Malh_coc02A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1970	1970	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
9856	1	No	No
Plan Irregularities		Vertical Irregularities	
Yes: Unknown		Yes: Unknown	
Falling Hazards		Poor Conditions	
Other: Light Cladding			
None			
None			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries