

City of Salem

Building Type	County
Fire - City	Marion
Street	
4000 Lancaster Dr (CCC Bldg 14)	
City	State Zip
Salem	OR 97305
Latitude	Longitude
44.97701	122.97852
Tracking Code	Inspection Date
RVS in 2006	7/31/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Salem Fire Dept - Station 08

Final RVS Score

Final Type	Final Score
RM1	0.7

FEMA-154 Collapse Potential

High (>10%)

No
Planview
Available



OregonGeology

Salem Fire Dept - Station 08

Mari_fir21A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1993	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	



W Elevation View



N Vertical Irregularity Primary



N Primary Structural Type
BRICK ON INSIDE OF FAR PIER



NW Elevation View



N Plan Irregularity Primary
ACCORDION WALLS ON SMALL SECTION



E Plan Irregularity Primary



E Elevation View



SE Elevation View



NE General Site
CMU TRAINING STRUCTURE



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries



S Vertical Irregularity Primary



SW Building Name