

Santiam Memorial Hospital - Stayton

Mari_hos02A

NFP - Santiam

Building Type		County	
Hospital		Marion	
Street			
1401 N 10th Ave			
City	State	Zip	
Stayton	OR	97383	
Latitude		Longitude	
44.8052		122.78484	
Tracking Code		Inspection Date	
RVS in 2006		9/18/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	0	0	-0.8	0	0	0.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Santiam Memorial Hospital - Stayton

Final RVS Score

Final Type

Final Score

W2

0.5

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1953	1953	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	Yes

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Single Change
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: Single Change (Adjacent Building/Entity)
None	None

Falling Hazards	Poor Conditions
Other: Brick Veneer	None
Unreinforced Chimneys	None
None	None



E Elevation View

N Vertical Irregularity Secondary
ROOF TRANSITION AND CHIMNEY

NW Plan Irregularity Primary



NW Plan Irregularity Primary



S Vertical Irregularity Secondary

Santiam Memorial Hospital - Stayton

Mari_hos02B

NFP - Santiam

Building Type		County	
Hospital		Marion	
Street			
1401 N 10th Ave			
City	State	Zip	
Stayton	OR	97383	
Latitude		Longitude	
44.80502		122.78474	
Tracking Code		Inspection Date	
RVS in 2006		9/18/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	0	1.6	-0.8	0	0	1.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Santiam Memorial Hospital - Stayton

Final RVS Score

Final Type

Final Score

C2

1.9

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Santiam Memorial Hospital - Stayton

Mari_hos02B

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1993	1953	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	Yes

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Building On Hill or Sloped Site
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: 2 to 3 Changes
None	Steps in Elevation View: Single Change (Adjacent Building/Entity)

Falling Hazards	Poor Conditions
None	None
None	None
None	None



S Vertical Irregularity Primary
CONN TO A - OFFICE CONST IS MASONITE W ALUM FRAME



S Primary Structural Type
1993 ADDN IS MOSTLY POLYSTYRENE FILLED W CONC AND BRICK VENEER ACC TO FACILITIES



E Vertical Irregularity Primary



E Other
CONN TO A - NO VI