

Accredited Training Providers

Program Name Accredited RRP NW

Address 365 Salem Heights Ave S

City State Zip Salem OR 97302

Phone 503-871-9754

Web www.accreditedrrpnw.com

Lead-Based Paint Activities Courses
--

Risk Assessor Initial:	No
Risk Assessor Refresher:	No
Inspector - Initial:	No
Inspector - Refresher:	No
Supervisor - Initial:	No
Supervisor - Refresher:	No
Project Designer - Initial:	No
Project Designer - Refresher:	No
Abatement Worker - Initial:	No
Abatement Worker - Refresher:	No

RRP Courses

Renovator - Initial:	Yes
Renovator - Refresher:	Yes
Dust Sampling Tech - Initial:	No
Dust Sampling Tech - Refresher:	No

Program Name American Contractors Organization

Address 11000 SW Barbur Blvd, Ste 100

City State Zip Portland OR 97219

Phone 971-645-4292

Web www.contractorsorganization.org

Lead-Based Paint Activities Courses
--

Risk Assessor Initial:	No
Risk Assessor Refresher:	No
Inspector - Initial:	No
Inspector - Refresher:	No
Supervisor - Initial:	No
Supervisor - Refresher:	No
Project Designer - Initial:	No
Project Designer - Refresher:	No
Abatement Worker - Initial:	No
Abatement Worker - Refresher:	No

RRP Courses

Renovator - Initial:	Yes
Renovator - Refresher:	Yes
Dust Sampling Tech - Initial:	No
Dust Sampling Tech - Refresher:	No

Program Name Crosswall Training/LeadClasses.com

Address 10350 N Vancouver Way #1021

City State Zip Portland OR 97217

Phone 888-840-8388

Web www.leadclasses.com

Lead-Based Paint Activities Courses
--

Risk Assessor Initial:	No
Risk Assessor Refresher:	No
Inspector - Initial:	No
Inspector - Refresher:	No
Supervisor - Initial:	No
Supervisor - Refresher:	No
Project Designer - Initial:	No
Project Designer - Refresher:	No
Abatement Worker - Initial:	No
Abatement Worker - Refresher:	No

RRP Courses

Renovator - Initial:	Yes
Renovator - Refresher:	Yes
Dust Sampling Tech - Initial:	No
Dust Sampling Tech - Refresher:	No

Program Name Environmental Testing and Training Northwest**Address** 2345 McGilchrist St SE #5**City State Zip** Salem OR 97302**Phone** 971-303-8378**Web** www.etnw.com**Lead-Based Paint Activities Courses****Risk Assesor Initial:** No**Risk Assesor Refresher:** No**Inspector - Initial:** No**Inspector - Refresher:** No**Supervisor - Initial:** Yes**Supervisor - Refresher:** Yes**Project Designer - Initial:** No**Project Designer - Refresher:** No**Abatement Worker - Initial:** Yes**Abatement Worker - Refresher:** Yes**RRP Courses****Renovator - Initial:** Yes**Renovator - Refresher:** Yes**Dust Sampling Tech - Initial:** No**Dust Sampling Tech - Refresher:** No

Program Name Oregon / SW Washington Painters, Drywall Finishers & Allied Trades Apprenticeship**Address** 13521 NE Whitaker Way**City State Zip** Portland OR 97230**Phone** 503-287-4856**Web** www.paintertraining.org**Lead-Based Paint Activities Courses****Risk Assesor Initial:** No**Risk Assesor Refresher:** No**Inspector - Initial:** No**Inspector - Refresher:** No**Supervisor - Initial:** No**Supervisor - Refresher:** No**Project Designer - Initial:** No**Project Designer - Refresher:** No**Abatement Worker - Initial:** No**Abatement Worker - Refresher:** No**RRP Courses****Renovator - Initial:** Yes**Renovator - Refresher:** Yes**Dust Sampling Tech - Initial:** No**Dust Sampling Tech - Refresher:** No

Program Name Oregon Home Builders Association**Address** 2075 Madrona St. Ste 150 SE**City State Zip** Salem OR 97302**Phone** 971-332-8409**Web** www.oregonhba.com**Lead-Based Paint Activities Courses****Risk Assesor Initial:** No**Risk Assesor Refresher:** No**Inspector - Initial:** No**Inspector - Refresher:** No**Supervisor - Initial:** No**Supervisor - Refresher:** No**Project Designer - Initial:** No**Project Designer - Refresher:** No**Abatement Worker - Initial:** No**Abatement Worker - Refresher:** No**RRP Courses****Renovator - Initial:** Yes**Renovator - Refresher:** Yes**Dust Sampling Tech - Initial:** No**Dust Sampling Tech - Refresher:** No

Program Name PBS Engineering and Environmental Inc

Address 4412 SW Corbett Ave
City State Zip Portland OR 97239
Phone 503-248-1939
Web www.pbsenv.com/service/training

Lead-Based Paint Activities Courses
--

Risk Assesor Initial:	Yes
Risk Assesor Refresher:	Yes
Inspector - Initial:	Yes
Inspector - Refresher:	Yes
Supervisor - Initial:	No
Supervisor - Refresher:	No
Project Designer - Initial:	No
Project Designer - Refresher:	No
Abatement Worker - Initial:	No
Abatement Worker - Refresher:	No

RRP Courses

Renovator - Initial: No
Renovator - Refresher: No
Dust Sampling Tech - Initial: No
Dust Sampling Tech - Refresher: No

Program Name Safety Directions LLC

Address 1528 Tamera Drive
City State Zip Klamath Falls OR 97603
Phone 541-205-3103
Web www.safety-directions.com

Lead-Based Paint Activities Courses
--

Risk Assesor Initial:	No
Risk Assesor Refresher:	No
Inspector - Initial:	No
Inspector - Refresher:	No
Supervisor - Initial:	No
Supervisor - Refresher:	No
Project Designer - Initial:	No
Project Designer - Refresher:	No
Abatement Worker - Initial:	No
Abatement Worker - Refresher:	No

RRP Courses

Renovator - Initial: Yes
Renovator - Refresher: No
Dust Sampling Tech - Initial: No
Dust Sampling Tech - Refresher: No

Program Name Tongue Point Job Corps Center

Address 37573 Old Hwy 30
City State Zip Astoria OR 97103
Phone 503-338-5006
Web tonguepoint.jobcorps.gov

Lead-Based Paint Activities Courses
--

Risk Assesor Initial:	No
Risk Assesor Refresher:	No
Inspector - Initial:	No
Inspector - Refresher:	No
Supervisor - Initial:	No
Supervisor - Refresher:	No
Project Designer - Initial:	No
Project Designer - Refresher:	No
Abatement Worker - Initial:	No
Abatement Worker - Refresher:	No

RRP Courses

Renovator - Initial: Yes
Renovator - Refresher: No
Dust Sampling Tech - Initial: No
Dust Sampling Tech - Refresher: No

Program Name Zack Academy, Inc
Address 2810 E Oakland Park Blvd, #200
City State Zip Ft. Lauderdale FL 33306
Phone 646-564-3546
Web www.zackacademy.com

Lead-Based Paint Activities Courses
--

RRP Courses

Renovator - Initial:	Yes	Risk Assesor Initial:	No
Renovator - Refresher:	No	Risk Assesor Refresher:	No
Dust Sampling Tech - Initial:	No	Inspector - Initial:	No
Dust Sampling Tech - Refresher:	No	Inspector - Refresher:	No
		Supervisor - Initial:	No
		Supervisor - Refresher:	No
		Project Designer - Initial:	No
		Project Designer - Refresher:	No
		Abatement Worker - Initial:	No
		Abatement Worker - Refresher:	No