## **Oregon Parks and Recreation Commission**

# February 27, 2024

Agenda Item: 8e Action

**Public Comment Allowed:** Yes

**Topic:** Silver Falls State Park Campground B Loop Restroom

Replacement

**Presented by:** James Robinson, Construction Project Manager

## **Background:**

• Staff request approval to award a construction contract not to exceed \$1,300,000.

- The project consists of demolishing the existing restroom building (built in 1987) and replacing it with a new ADA compliant restroom building. The new building will contain 10 gender-neutral rooms (four toilet rooms, four shower rooms, and two rooms with a toilet and shower)
- Project was selected due to high annual use and building fatigue.
- The design team completed the construction documents and submitted them to OPRD on January 31st, 2024.
- The budget for this project is currently \$1,200,000. Funding will come from the OPRD Policy Option Package 108.
- Silver Falls State Park Campground B Loop Restroom Replacement timeline:
  - o Design phase: Complete
  - o Project approval: February 15<sup>th</sup> 2024 April 15<sup>th</sup>, 2024
  - o Bidding: April 16<sup>th</sup> 2024 June 5<sup>th</sup>, 2024
  - o Contract: June 6<sup>th</sup> 2024 July 22<sup>nd</sup>, 2024
  - o Construction: September 16<sup>th</sup>, 2024 January 13<sup>th</sup>, 2025

**Prior Action by Commission:** None

**Action Requested:** Approval of contract not to exceed \$1,300,000.

#### **Attachments:**

- Attachment A: Preliminary Plans (Existing and Proposed Site Plan)
- Attachment B: Existing Photos

Prepared by: James Robinson, Construction Project Manager

# Attachment A Preliminary Plans (Existing and Proposed Site Plan)




Figure A – Existing/Demo Site Plan




Figure B – Proposed Site Plan




Figure C – Proposed Building Floor Plan

# Attachment B Existing Photos



**Figure 1 – Existing Restrooms.** 



Figure 2 – Existing infrastructure corral adjacent to restroom.



Figure 3 – Electrical and plumbing equipment in need of replacement.



Figure 4 – Aging fixtures and finishes, difficult to maintain and clean.



Figure 5 – Patches in paving, non-ADA path