

Instructions: This form is used during drilling or workover operations of testing, coring, or perforating, and a formation name in describing work performed. Number all drill stem tests sequentially. Attach description of all cores. Work performed by Producing Section will be reported on "Interim" sheets until well completion. Report official or representative test on "Final" form. Submit "Interim" sheets when filled out but not less frequently than every 30 days, or 2, on Wednesday of the week in which oil string is set. Submit weekly for workovers and following setting of oil string until completion.

District WESTERN	County or Parish COLUMBIA COUNTY	State OREGON
Field MIST	Lease or Unit COLUMBIA COUNTY	Well no. 22-27

Date and depth as of 8:00 a.m. 6:00 a.m.	Complete record for each day while drilling or workover in progress 1985
---	---

11-26	COLUMBIA COUNTY #22-27 - (Mist) - Taylor #4 - AFE # R46087 PBD: 0' - Release Rig RIH open ended to 525'. Mix and pump 80 sx Class G + 2% CaCl <sub>2</sub> mixed at 15.8 ppg. CIP at 1330 hrs, 11-25-85. POOH. Tag TOC at 335'. ND BOP. RIH to 61'. Mix and pump 20 sx Class G mixed at 15.8 ppg. Cement to surface. <u>Release rig at 2230 hrs 11-25-85.</u>	AET
-------	--	-----

The above is correct		
Signature B. E. DAVIS	Date	Title DISTRICT DRILLING SUPERVISOR

For form preparation and distribution see Procedures Manual Section 10, Drilling, Pages 86 and 87