

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS

(Do not use this form for proposals to drill or to deepen or plug
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL GAS WELL OTHER

Abandoned Exploratory

2. NAME OF OPERATOR

Texaco Inc.

3. ADDRESS OF OPERATOR

3350 Wilshire Blvd., Los Angeles

4. LOCATION OF WELL (Report location clearly and in accordance with a
See also space 17 below.)
At surface

1605' North and 1036' East of
Corner of Sec. 31, T17S, R23E

14. PERMIT NO.

63

15. ELEVATIONS (Show whether

4060' GL (

16.

Check Appropriate Box To Indicate

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent
proposed work. If well is directionally drilled, give subsurface location
pertinent to this work.) *

The following work has been completed

1. Surface location has been cleared

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS

(Do not use this form for proposals to drill or to deepen or
Use "APPLICATION FOR PERMIT—" for

1.

OIL WELL GAS WELL OTHER Wildcat

2. NAME OF OPERATOR

Texaco Inc.

3. ADDRESS OF OPERATOR

P. O. Box 3337, Ventura, Cal

4. LOCATION OF WELL (Report location clearly and in accordance with
See also space 17 below.)

At surface

1605'

1065' N & 1036' E from SW Cor. of
T17S, R23E, of WB&M

14. PERMIT NO.

15. ELEVATIONS (Show whether

4006 GR

16.

Check Appropriate Box To Indicate

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all proposed work. If well is directionally drilled, give subsurface
nent to this work.)*

See attached which describes