

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE (Other instructions on reverse side)

Form approved. Budget Bureau No. 42-R1424.

LEASE DESIGNATION AND SERIAL NO.

OCS PO-103

IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL [ ] GAS WELL [ ] OTHER Dry Hole
2. NAME OF OPERATOR Standard Oil Company of California, Western Operations, Inc.
3. ADDRESS OF OPERATOR Exploration Dept., P.O. Box 250, Seattle, Washington 98111
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.) At surface Lambert Coordinates, Oregon North Zone X = 1,020,659 Lat. = 44°51'28.182" Y = 457,162 Long. = 124°16'41.337"
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 33' DF
9. WELL NO. Nautilus #1
10. FIELD AND POOL, OR WILDCAT Wildcat
11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA Block #74
12. COUNTY OR PARISH 13. STATE Offshore Oregon

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO: TEST WATER SHUT-OFF [ ] FILL OR ALTER CASING [ ] WATER SHUT-OFF [ ] REPAIRING WELL [ ]
FRACTURE TREAT [ ] MULTIPLE COMPLETE [ ] FRACTURE TREATMENT [ ] ALTERING CASING [ ]
SHOOT OR ACIDIZE [ ] ABANDON\* [ ] SHOOTING OR ACIDIZING [ ] ABANDONMENT\* [X]
REPAIR WELL [ ] CHANGE PLANE [ ] (Other) [ ]
(NOTE: Report results of multiple completion on Well Completion or Recombination Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)
TD 12,627', 30" at 522'; 13-3/8" at 1414'; 10-3/4" at 3235'.
Hole full of 80 pcf. mud.
The following work was performed:
1. Went in with open ended drill pipe, equalized 100 sacks cement (220') at 11,100'. Top Density Tool Fish at 11,105'. Dropped junk on top of plug.
2. Equalized 147 sacks cement across 10-3/4" casing shoe at 3235'. Located top cement at 3100'; tested with 20,000 lbs. pipe weight. OK.
3. Equalized 50 sacks cement at 625'; pulled to 585'.
4. Shot off all casing strings 20' below ocean floor. Pulled tensioner, riser, BOP, and main base and casing ends.
5. Sub-base sunk into ocean floor; unable to recover; TV disclosed 2 posts 12" above ocean floor. Displaced 300 sacks cement with 2% gel on top of sub-base.
6. Well abandoned and barge released 11:00 P.M. August 5, 1965. Casing in hole following depths, DF measurement. 30" from 472'-522'; 13-3/8" from 472'-1414'; 10-3/4" from 472'-3235'.

18. I hereby certify that the foregoing is true and correct
SIGNED D. N. Helmutz, TITLE Lead Development Geologist DATE 8-16-65

(This space for Federal or State office use)
APPROVED BY J. H. Luebber, TITLE Los Angeles District Engineer DATE SEP 1 1965

SEP 20 1965 CYPHER

NOTED SEP 20 1965 SCHAMBECK

\*See Instructions on Reverse Side

NOTED SOLANAS

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE (Other instructions on reverse side)

Form approved. Budget Bureau No. 42-R1424.

LEASE DESIGNATION AND SERIAL NO.

OCS PO-103

IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL [ ] GAS WELL [X] OTHER Dry Hole
2. NAME OF OPERATOR Standard Oil Co of California, WOT
3. ADDRESS OF OPERATOR PO Box 250, Exploration Dept, Seattle, Washington 98111
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.) At surface Lambert Coordinates, Oregon North Zone X=1,020,659, Y=457,162 Lat=44°51'28.182" Long=124°16'41.337"
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 33' DF
9. WELL NO. Nautilus #1
10. FIELD AND POOL, OR WILDCAT Wildcat
11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA Block #74
12. COUNTY OR PARISH 13. STATE Offshore Oregon

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO: TEST WATER SHUT-OFF [ ] FILL OR ALTER CASING [ ] WATER SHUT-OFF [ ] REPAIRING WELL [ ]
FRACTURE TREAT [ ] MULTIPLE COMPLETE [ ] FRACTURE TREATMENT [ ] ALTERING CASING [ ]
SHOOT OR ACIDIZE [ ] ABANDON\* [X] SHOOTING OR ACIDIZING [ ] ABANDONMENT\* [ ]
REPAIR WELL [ ] CHANGE PLANE [ ] (Other) [ ]
(NOTE: Report results of multiple completion on Well Completion or Recombination Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Status: Depth 12,625' Running Junk Basket, Will Log and possibly drill or core while waiting on Approval.
30" @ 522'
13 3/8" @ 1414' Previous Log Run To 11,566'
10 3/4" @ 3235' Water Depth 419'

Program: 1. Hole will be full of 80.92 lb/ft³ mud.
2. Place 300 lineal ft. cement plug Across shoe of 10 3/4" casing @ 3235'.
3. Test Plug w/ minimum 15,000 lbs. pipe weight.
4. Place 50 sack cement plug 50' below ocean Floor in 10 3/4" casing.
5. Shoot off casing strings 20' below ocean Floor.
6. Recover Main Base.

There Are no Fresh water, Oil, or Gas Sands To Isolate. All casing will be recovered To a Depth greater Than 3' below ocean Floor, and ocean Floor cleared of obstructions.

18. I hereby certify that the foregoing is true and correct
SIGNED E. G. Dobrick, Jr. by D. N. Helmutz, TITLE Lead Development Geologist DATE 7-29-65

(This space for Federal or State office use)
APPROVED BY J. H. Luebber, TITLE Los Angeles District Engineer DATE AUG 3 - 1965

\*See Instructions on Reverse Side

NOTED AUG 4 - 1965 SCHAMBECK

GEOLOGICAL SURVEY RECEIVED AUG 2 1965 LOS ANGELES