

COMPANY MOBIL OIL CORPORATION
 WELL SUTHERLIN UNIT NO. 1
 FIELD WILDCAT
 COUNTY DOUGLAS STATE OREGON
 LOCATION 455, 715 SOUTH & 2064, 61 EAST FROM THE WEST 1/4 CORNER OF SECTION 36 24S 5W
 SERIAL NO. 36 TWP. 24S RANGE 5W
 Other Services: DIL BHC HRT 10D FDC/CNL/GR CBL

Permanent Datum: GL Elev.: 488
 Log Measured From: KB Elev.: 488
 Drilling Measured From: KB Elev.: 488

Run No. 10-19-78
 Depth-Driller 3624
 Depth-Loggers (Schl.) 3627
 Bim. Log Interval 3626
 Top Log Interval 1860
 Casing-Driller 16" @ 1858 @
 Casing-Logger 1860 @

Type Fluid in Hole L/GANOSULFONATE
 Dens. Visc. 20.5 93
 pH Fluid Loss 12.5 10.6 ml
 Source of Sample
 Run @ Meas. Temp. @ @ @ @ @ @
 Rmt @ Meas. Temp. @ @ @ @ @ @
 Rmc @ Meas. Temp. @ @ @ @ @ @
 Source Rmt Rmc @ @ @ @ @ @
 Run @ BHT @ @ @ @ @ @
 Circulation Stopped 0400
 Logger on Bottom 0830
 Max. Rec. Temp. 109 F
 Equip. Location 7758 SAC
 Recorded By BRASEFIELD
 Witnessed By M. BOOZER

SCALE CHANGES
 Type Log _____ Depth _____ Scale Up Hole _____ Scale Down Hole _____
 Run No. 096
 Service Order No. 64702
 API Serial No. _____
 Fluid Level FULL
 EQUIPMENT DATA
 EQPT. TYPE BGT
 PANEL NO. BGP-0770
 CART NO. 771
 SONDE NO. 778
 PTR NO. _____
 G.P. PANEL NO. _____
 CENT. DEVICE _____
 CALIBRATION DATA
 Speed - F.P.M. 67
 GR BKG. CPS
 Source CPS
 Tc

All interpretations are opinions based on inferences from electrical or other measurements and we cannot, and do not guarantee the accuracy or correctness of any interpretations, and we shall not, except in the case of gross or willful negligence on our part, be liable or responsible for any loss, costs, damages or expenses incurred or sustained by anyone resulting from any interpretation made by any of our officers, agents or employees. These interpretations are also subject to Clause 4 of our General Terms and Conditions as set out in our current Price Schedule.

