

Eligibility Requirements for Lead-based Paint Professionals

Inspector Requirements:

- Training: Successfully complete and receive a course completion certificate from an accredited Lead-Based Paint Inspector training course which consist of 24 contact hours with at least 8 hours of hands-on training.
- Experience: None
- Education: None
- Examination: Pass the certification examination administered by the Department for Inspector.

Risk Assessor Requirements:

- Training: Successfully complete and receive a course completion certificate from an accredited Lead-Based Paint Risk Assessor training course which consist of 16 contact hours with at least 4 hours of hands-on training and successfully complete and receive a course completion certificate from an accredited Lead-Based Paint Inspector training course.
- Education & Experience: Certification as an industrial hygienist, an engineer, a registered architect, certified safety professional, registered sanitarian, or registered environmental health specialist; or
A bachelor's degree *and* one year of experience in a related field (e.g. lead, asbestos, environmental remediation work, or construction); or
An Associates degree *and* two years of experience in a related field (e.g., lead, asbestos, environmental remediation work, or construction); or
A high school diploma (or equivalent), *and* at least 3 years of experience in a related field (e.g., lead, asbestos, environmental remediation work, or construction).
- Examination: Pass the certification exam administered by the Department for Risk Assessor.

Supervisor Requirements:

- Training: Successfully complete and receive a course completion certificate from an accredited Lead-Based Paint Abatement Supervisor training course.
- Experience: One year of experience as a certified Lead-Based Paint abatement worker; or
At least two years of experience in a related field (e.g., lead, asbestos, or environmental remediation work) or in the building trades.
- Education: None
- Examination: Pass the certification exam administered by the Department for Supervisor.

Abatement Worker Requirements:

- Training: Successfully complete and receive a course completion certificate from an accredited Lead-Based Paint Worker training course.
- Experience: None
- Education: None
- Examination: None

Project Designer Requirements:

- Training: Successfully complete and receive a course completion certificate from an accredited Lead-Based Paint Project Designer training course.
- Education & Experience: A Professional Engineering license and one year of project management experience in building construction or renovation, or related field.
A bachelor's degree in engineering, architecture, or certification as a Remodeler and two years of project management experience in building management involving lead-based paint, asbestos, or hazardous materials.
- Examination: Pass the certification examination administered by the Department for Project Designer.

