



Oregon

Theodore R. Kulongoski, Governor

Department of Transportation

Technical Services

Roadway Engineering Section

355 Capitol Street NE, Room 222

Salem, OR 97301-3871

Telephone 503-986-3714

FAX 503-986-3749

DATE: February 9, 2009

Addenda No. 2

TO: PLAN HOLDERS

PREPARED BY: Shane Terwilliger
Shane Terwilliger PLS.

APPROVED BY: Carol A. Cartwright
Carol Cartwright PE

SUBJECT: I-5: Surface Mounted Pavement Markers Section
Pacific Highway
Various Counties
Pavement Markings Project
(Bids to be opened and read February 19, 2009)

The following changes are made to the Project Bid Booklet:

1. The following changes are made to the Project Bid Items:

Added items:

<u>Number</u>	<u>Item</u>	<u>Unit</u>	<u>Quantity</u>
0120	Repair Temporary Impact Attenuator, Truck Mounted	Each	2

Make a copy of and use the new attached Bid Sheets. A Bid **not** including these new Bid Sheets **will be rejected as non-responsive**.

The following changes are made to the Project Special Provisions:

1. Subsection **00225.62(b) Temporary Impact Attenuators** - This subsection is replaced with the following subsection:

00225.62(b) Temporary Impact Attenuators - Replace the paragraph that begins "When impact attenuator..." with the following paragraph:

When impact attenuator, truck mounted attenuator, or narrow site attenuator systems are used, have enough modules, cartridges, components, and replacement parts on-site to replace one complete installation or have on-site a complete replacement attenuator. Re-stock replacement items or complete replacement attenuators within 24 hours of use.

All modules, cartridges, components, and replacement parts, and replacement attenuators not used remain the property of the Contractor.

Repair of damage to vehicles utilizing truck mounted attenuators will be at no additional cost to the Agency.

2. Subsection **00225.82(e) Temporary Impact Attenuator Repair** - This Subsection is added after Subsection 00225.62(b):

00225.82(e) Temporary Impact Attenuator Repair - Temporary impact attenuator repair will be measured on the unit basis.

3. Subsection **00225.90(a-1) Pay Quantities** - This Subsection is added after Subsection 00225.82(e):

00225.90(a-1) Pay Quantities - Replace the paragraph that begins "All TCD damaged by..." with the following paragraph:

All TCD damaged by public traffic and replaced by the Contractor, except temporary signing, temporary electrical signs, and portable temporary traffic signals, will be paid for at the Contract price for the pay items listed in the Contract Schedule of Items or in approved Contract change orders, unless otherwise specified. Payment for replacing damaged TCD will only be made when:

4. Subsection **00225.92 Temporary Barricades, Guardrail, Barrier, and Attenuators** -
This subsection is replaced with the following subsection:

00225.92 Temporary Barricades, Guardrail, Barrier, and Attenuators - Add the following pay item to the end of the pay item list and add the following paragraph:

(n) Repair Temporary Impact Attenuator, _____Each

In item (n), the type of attenuator, if applicable, will be inserted in the blank. Item (n) includes repair or complete replacement of impact attenuators damaged by public traffic. Replace the paragraph that begins "No separate or additional..." with the following paragraph:

No separate or additional payment will be made for temporary impact attenuator replacements, replacement modules, cartridges, components, or replacement parts that are required to be on-site according to 00225.62(b).

No separate or additional payment will be made for moving truck mounted impact attenuators or for truck mounted attenuator vehicle damage.

These changes will be included in the Contract for this Project. It is understood that your Bid will be submitted accordingly.

Make copies of the new Bid Sheets to replace the Special Provisions Bid Schedule Sheets.

BID SCHEDULE

CONTRACT ID: 13979

PROJECT: I-5: SURFACE MOUNTED PAVEMENT MARKERS

PROJECT KEY: 14931

ADDENDUM NUMBER: 2

ITEM NO	ITEM DESCRIPTION	QUANTITY AND UNITS	UNIT PRICE (IN FIGURES)	BID AMOUNT (IN FIGURES)
---------	------------------	--------------------	----------------------------	----------------------------

SECTION 0001 TEMPORARY FEATURES AND APPURTENANCES

0010	0210-0100000A MOBILIZATION	LS	ALL	
0020	0225-0100000A TEMPORARY PROTECTION AND DIRECTION OF TRAFFIC	LS	ALL	
0030	0225-0102000J TEMPORARY SIGNS	SQFT	100.00	
0040	0225-0138000E TEMPORARY IMPACT ATTENUATOR, TRUCK MOUNTED	EACH	3.00	
0050	0225-0162000E SEQUENTIAL ARROW SIGNS	EACH	2.00	
0060	0290-0100000A POLLUTION CONTROL PLAN	LS	ALL	

SECTION 0002 ROADWORK

0070	0305-0100000A CONSTRUCTION SURVEY WORK	LS	ALL	
0080	0310-0106000A REMOVAL OF STRUCTURES AND OBSTRUCTIONS	LS	ALL	

SECTION 0003 PERMANENT TRAFFIC SAFETY AND GUIDANCE DEVICES

0090	0000-0100000A DELETED BID ITEM	LS	ALL	0.00	0.00
------	-----------------------------------	----	-----	------	------

BID SCHEDULE

CONTRACT ID: 13979

PROJECT: I-5: SURFACE MOUNTED PAVEMENT
MARKERS

PROJECT KEY: 14931

ADDENDUM NUMBER: 2

ITEM NO	ITEM DESCRIPTION	QUANTITY AND UNITS	UNIT PRICE (IN FIGURES)	BID AMOUNT (IN FIGURES)
0100	0855-0106000E MONO-DIRECTIONAL WHITE TYPE 1AR MARKERS, RECESSED	EACH	39,723.00	

SECTION 0004 ADDED BID ITEMS

0110	0280-0100000A EROSION CONTROL	LS	ALL	
0120	0225-0141400E REPAIR TEMPORARY IMPACT ATTENUATOR, TRUCK MOUNTED	EACH	2.00	
	TOTAL BID			