

Activity 094 Asbestos Removal

Description

Activity 094 involves identifying, testing, removing, and disposing of asbestos found on ODOT property. It includes the costs of removing and disposing of the involved material, monitoring of health and the environment, consultant fees, laboratory analyses, and fines from regulatory or other agencies.

General Information

Refer to discussion in the General Instructions section preceding Activity 014 in this section of the *Maintenance Guide* for additional information including environmental and traffic control recommendations and other important considerations.

Seek assistance from the District Manager, ODOT Industrial Hygienist in the Office of Employee Safety, Region Hazmat Coordinator, and Region Environmental Coordinator as needed.

Only specially trained persons may perform this work. Do not perform the work without the required training and protective devices.

Before beginning the work, obtain a Special EA from the Maintenance Management System (MMS) Unit in the ODOT Transportation Program Office.

Follow accepted practices to obtain consultants, laboratory analyses, etc. Refer to the Purchase and Acquisition of Goods and Services section of this Guide.

Measurement of Accomplishment, Expenditure Account, Charge Activity

Measurement is number of worker hours involved. Expenditure account type is Special EA.

- Charge all costs to Activity 094.