

## **Activity F20 Fleet Supplies**

### Description

Activity F20 involves performing inspection, service, or repair of equipment that is not attributable to a specific piece of equipment. It includes all costs of labor, supplies, tools, and miscellaneous shop expenses.

### General Information

Refer to discussion in the General Instructions section preceding Activity 014 in this section of the *Maintenance Guide* for additional information including environmental and traffic control recommendations and other important considerations.

Refer to Activities F25, F30, and F34 through F43 for work or costs related to a specific piece of equipment, either in the ODOT rental fleet or leased.

Also refer to the Equipment section of this Guide.

### Measurement of Accomplishment, Expenditure Account, Charge Activity

Measurement is number of worker hours involved. Expenditure account type is Crew IN (indirect) EA; use a sub job appropriate for the crew performing the work.

- Charge all costs to Activity F20.