


PLAN AND SECTIONS OF SHAFT 1 WORKINGS AND PLAN OF SHAFT 2 WORKINGS, AXE HANDLE MINE, JEFFERSON COUNTY, OREGON

Geology by R. E. Brown and G. W. Walker, 1943

903601 O - 51 (In envelope) No. 16



51  
11  
13

10

10

