GREAT HERAL. GANYON MT. REGION (See Goed quary Veins CANYON DIST. Banyon District)

na series and a series and a series and a series and a series of the series of the series of the series of the
en e
and a second s Second second
a de la companya de l An
A state of the second s
n en
n an
en e
•

					6/
Great Northern Mi NAME	OLD NAMES		Gold PRINCIPAL OR	P NTNOD	AL TRUCK AT A
2 mi. S.E. Canyon City			TAINUITAL UR	e Minor	MINERALS
T14S R32E T R	<u> </u>	regon Metal Mine	ISHED REFERENCES es Handbook 14B:24	•	
	• P	arks & Swartley	16:111-112		
Grant	County				
Canyon	AREA		•		· · ·
4700	ELEVATION	MISC	ELLANEOUS RECORDS		
	ROAD OR HIGHWAY				
about 26.mi. Seneca	DISTANCE TO SHIPPING POINT	,			
RESENT LEGAL OWNER (S)	Isaac Guker	Addre	ess Canyon Vity Ore .	• • • • • • • • • • • • • • • • • • • •	•••••
		•••••	• • • • • • • • • • • • • • • • • • • •	• • • • • • • • • • • • • • • • • • • •	• • • • • • • • • • • • • • • •
	• • • • • • • • • • • • • • • • • • • •	• • • • • • •		• • • • • • • • • • • • • • • • • • • •	• • • • • • • • • • • • • •
	• • • • • • • • • • • • • • • • • • • •	• • • • • •	• • • • • • • • • • • • • • • • • • • •		•••••
PERATOR		• • • • • •			• • • • • • • • • • • • •
Name of claims	Area Pat. Unpat.		Name of claims	Area Pat.	Unpat.
					•
	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~			<del>، ، ، ، ، ، ، ، ، ، ، ، ، ، ، ، ، ، ، </del>	
	<u> </u>				
EQUIPMENT ON PROPERTY					

GREAT NORTHERN MINE (Gold)

Canyon Area

Owner: Isaac Guker, Canyon City, Oregon.

- Location: This mine is located about 2 miles southeast of Canyon City on the steep north slope of Canyon Mountain, about 1500 feet above the town, at an elevation of 4700 feet.
- History: In 1898 a \$30,000 pocket was extracted from one of the seams in a surface cut on this property. Prospecting operations have since been carried on rather extensively underground in search of other pockets. A few pockets of much less importance have since been found.
- Geology: The country rock is greenstone (gabbro) and diabase-porphyry. A quartz vein 1 to 2 feet thick, striking N and S and dipping 25° W, is practically barren, although it contains pyrite and seams of calcite. Another barrier vein 2 feet wide strikes east and west and dips 35° S. The valuable gold deposits on this, as well as most other properties on Canyon Mountain, are not found in the quartz veins, but rather in quartz-calcite seams, which are quite numerous everywhere. Valuable pockets are occasionally found in quartz seams closely associated with calcite. Reference: Parks and Swartley 16:111-112.