

LITTLE JOHNNY (gold)

Gold Hill area

Owner: Richard Keif, Gold Hill, R.D. no. 1, Oregon.

Location: sec. 28, T. 36 S., R. 3 W., just above county road on Galls Creek.

Area: 40 acres, deeded land, purchased from Jackson County.

Development: 800 feet of workings included in two tunnels and 4 winzes. The winzes were full of water when inspection was made, and some of the tunnels were unsafe.

Geology: The country rocks are granite and meta-igneous rock. The meta-igneous rock, as well as quartz stringers and some of the granitoid rock is impregnated with pyrite, and a little chalcopyrite. Mr. Keif states that tellurides are present.

Equipment: 20-hp. gasoline compressor, 2 jack hammers, 300 feet of light rails, $\frac{1}{2}$ -ton car, 2-inch hand pump.

General: The owner believes the ore deposits on this property are extensions of those of the adjoining Braden Mine. Considerable more work is necessary in order to prove a relation between the deposits of the two properties.

Infermant: Richard Keif.

Report by: R. C. T., February 20, 1940.