

6/46

Armco Drainage & Metal Products, Inc.

NAME	OLD NAMES	PRINCIPAL ORE	MINOR MINERALS
Ontario, Oregon			
Nyssa, Oregon			

PUBLISHED REFERENCES

T R S

..... Malheur COUNTY

..... Unclassified AREA

..... ELEVATION

..... ROAD OR HIGHWAY

..... DISTANCE TO SHIPPING POINT

MISCELLANEOUS RECORDS

PRESENT LEGAL OWNER (S) .. Hardesty Division Armco Drainage & Metal Products, Inc. Address .. P.O. Box 2170, Denver, Colorado

.....

.....

OPERATOR Hardesty Division Armco Drainage & Metal Products, Inc.

Name of claims	Area	Pat.	Unpat.	Name of claims	Area	Pat.	Unpat.

EQUIPMENT ON PROPERTY

FW

State Department of Geology and Mineral Industries

702 Woodlark Building
Portland, Oregon

Report by: N. S. W.
Date: April 17, 1946

Armco Drainage & Metal Products, Inc., -Ontario Plant

Malheur County
Unclassified District

Old Name: Ontario Concrete Pipe Company

Owner-Operators: Hardesty Division
Armco Drainage & Metal Products, Inc.
P.O. Box 2170, Denver, Colorado

Location: Ontario, Oregon; Mr. J. Updegraff, Mgr.

General: This plant manufactures a complete line of concrete pipe, and in addition handles metal culverts and piping made by the parent company. The concrete pipe produced in this plant includes the following types and sizes:

sewer-4" to 24"

irrigation-4" to 18"

plain and re-inforced culvert-to 54"

Equipment includes a Stearns mixer and a Tuerch MacKenzie Pipe machine.

An average of six men is maintained at this plant and normal materials requirements is 50 sacks of cement and 9 yards of aggregates per 8 hour day.

RECEIVED
APR 23 1946
STATE DEPT OF GEOLOGY
& MINERAL IND.

Flw

State Department of Geology and Mineral Industries

702 Woodlark Building
Portland, Oregon

RECEIVED
MAY 13 1946

STATE DEPT OF GEOLOGY
& MINERAL INDS.

Confidential Report To Accompany Report On Nyssa Tile & Pipe Co.
By N. S. W. April 17, 1946

I didn't get to meet Mr. Johnson personally when I inspected his plant as he was out of town, but the general layout of his buildings and the quality of the workmanship on the plant as described in the report was such as to indicate Mr. Johnson to be a sound and competent person with high standards and one who knows his business as far as putting up a modern, efficient plant. As is, it is my understanding that he is operating on a shoe string financially and that Armco set his plans back materially when they bought a site and built their plant directly across the street from him. At present, plans are underway for refinancing this venture, which, I believe will be necessary before it can be completed.

CONFIDENTIAL