

STATE OF OREGON
DEPARTMENT OF GEOLOGY AND MINERAL INDUSTRIES

800 NE Oregon St #28 Portland, OR 97201

PLUGGING RECORD
(In compliance with rules and regulations pursuant to ORS 520)

Enerfin Resources Northwest

"Columbia County"

44-08-64 (Windy Hill)

(Company or Operator)

(Lease)

(Well No.)

Sec. 8 T 6N R 4W Surveyed Coordinates:

SHL= 869.75' North and 830.81' West from the Southeast corner of Section 8

BHL= _____

Wildcat: NA Field Name: Mist Gas County: Columbia

Date well was plugged: August 18, 1999

The interval between plugs shall be filled with a heavy mud-laden fluid. Was the well filled with mud-laden fluid as required? Yes

How was the mud applied? Circulated

Please furnish the following information:

CASING:	(1) Size	(2) Weight	(3) Depth set	Plugs:	(1) Type	(2) Depth/interval	(3) Amount of cement
	8-5 8"	24#	511'		Cement	1.15"-79"	25 sx
	4-1 2"	10.5#	1,314'		Cement	25'-surface	5 sx

AFFIDAVIT

STATE OF Oregon

County of Columbia

I, Rob Lucas being first duly sworn, depose and say that I have knowledge of the facts stated herein, that they are true and correct, and that I am authorized to make this report.

Signature: _____

Position: Consultant

Subscribed and sworn to before me this _____ day of _____, 19 _____

Signature: _____

My commission expires _____ Notary Public for State of _____