## STATE OF OREGON DEPARTMENT OF GEOLOGY AND MINERAL INDUSTRIES 1069 State Office Building Portland 1, Oregon

## HISTORY OF OIL OR GAS WELL

RECEIVED-PTLD

(Submit in duplicate)

DEC 21 1981

DEPT OF GEOL 10 In compliance with rules and regulations adopted pursuant to ORS 520.095 (Chapter 667 OL 1953)

Operator

Reichhold Energy Corp.

Field Mist.

Well No.

Hansen 44-15

, Sec. 15 , T. 6N

W. B. & M.

Signed I im Williams

R.

5W

Date 12-8-81 Title Drilling Superintendent (President, Secretary or Agent)

It is of the greatest importance to have a complete history of the well. Use this form in reporting the history of all important operations at the well, together with the dates thereof, prior to the first production. Include in your report such information as size of hole drilled to cementing or landing depth of casings, number of sacks of cement used in the plugging, number of sacks or number of feet of cement drilled out of casing, depth at which cement plugs started, and depth at which hard cement encountered. If the well was dynamited, give date, size, position and number of shots. If plugs or bridges were put in to test for water, state kind of material used, position and results of pumping or bailing.

Date 10-26-81

10-27-81

11- 1-81

11- 2-81

Spudded well drilling 9 7/8 surface hole.

Finished drilling surface hole, ran 11 JTs of 7" 17# casing to 442.18 as measured from Kelly Bus hing cemented same with 200 SXs of class G cement. Bumped plug with full cement returns.

Waiting 24hrs. for cement to cure, tested BOP's 10-28-81 10-29-81

Drilling 6 1/4 hole Depth 934 10-30-81

1690 Ħ п 2143

П 2782 finished drilling & logging well

11- 3-81 Logging

11- 4-81 Plugging well to abandon

1st plug 2782 - 2000

11- 5-81 2nd plug set @ 642 - 342'

Left 10 plug @ top and abandoned well