

RECEIVED-PTLD
DEC 21 1981

PLUGGING RECORD

The owner or operator of any oil or gas well or stratigraphic hole shall file this form with the Director of the State of Oregon Department of Geology and Mineral Industries setting forth in detail the method used in plugging such well. The form must be filed within twenty (20) days after plugging for oil and gas wells, or within sixty (60) days for stratigraphic holes.

Rule L of rules and regulations adopted pursuant to ORS 520.095 (1) (13) (Chapter 667 OL 1953)

Operator Reichhold Energy Corp. Field Mist
Pool Clark & Wilson
County Columbia County

ADDRESS ALL CORRESPONDENCE CONCERNING THIS FORM TO:

Street P.O. Box 810 City St. Helens State Oregon
Lease Name Hansen Well No. 44-15 Sec. 15 T. 6N R. 5W
Date well was plugged 11-3- 19 81.

Was the well filled with mud laden fluid, according to regulations of the Board of the State of Oregon Department of Geology and Mineral Industries? Yes

How was the mud applied? Pumped Were plugs used? Yes If so, show all shoulders left for casing, depth of each, and size of casing, size and kind of plugs used, and depths placed. Also amount of cement and rock.
Use additional sheets if necessary.

1st plug 2782' - 2000'

2nd plug 642 - 342

Was notice given, before plugging, to all available adjoining lease and land owners? Yes

Reichhold Energy Corporation
(Operator)

AFFIDAVIT

State of OREGON
County of Columbia

I, Tim Williams, being duly sworn, say that I have knowledge of the facts stated herein, that they are true and correct, and that I am authorized to make this report.

Subscribed and sworn to before me this 15th day of December 19 81

Notary public in and for said State Carol A. Cross

My commission expires 10-8-85.