to the party of

1659 State Office Building Portland 1, Oregon

| MISCELLANEOUS NOTICES AND REPORT | S ON WELLS AND STRATIGRAPHIC HOLES n triplicate) |
|--|--|
| This is a combined form, use o | only portions pertinent to your needs. |
| o comply with rules and regulations adopted pursuant to ORS | 520 (Chapter 667 OL 1953) |
| Notices | Reports |
| en a state of notice by checking below: | Indicate nature of report by checking below: |
| to the steption to plug well. the type to pende formation test. | Report on plugging well (use form 5) |
| City on to under formation test | Report on making founation test Report on making production test |
| Section 1999 to enthe production test | X Report on abandoning well |
| of grantion to test casing shut-off | Report on testing casing sout-off Report on redrilling or deepening well |
| to sentencial to redrill or deepen well- | Report on shooting or chemically treating well |
| is a secretar to complete well | Report on completion of well |
| | |
| limit makings in triplicate before the work specified is to egip. A copy will be returned to the sender on which will given the approval, with any modifications considered dissole, or the rejection by the Department or agent, of e plan submitted. | Submit reports in triplicate within 20 days after the work specified is completed. ANTERCELEI D. CA NOVEMBER 24 40.80 |
| <u>B</u> . | AKERSFIELD, CA, STEEN, NOVEMBER 24. 1980 |
| epartment of Geology and Mineral Industries | OREGON NATURAL GAS |
| ortland, Oregon | DEVELOPMENT CORPORATION |
| ollowing is a report on the work done and the results obtained notice of intention to do certain work as describ | hed helow at the |
| INDEPENDENCE | Well No. 12-25 in NW/4 |
| Lease | Well Hot |
| of - OC - A W was | 3. G.M.,field, |
| | |
| MARION County. T | he dates of this work were as follows NOVEMBER 23,1980. |
| origin of intention to do the work was (was not) submitted on f and approval of the proposed plan was (was not) obtained. (Cro | orm on 19oss out incorrect words.) |
| he present condition of the well, including complete casing r | ecord, is as follows (Use additional sheets as needed): |
| 7" surface casing cemented 635'. 6-1/4" hole drilled to 4826'. No oil or gas sands were found. | |
| TTAC BY IS A COMPLETE DETAILED ACCOUNT OF PRO | OPOSED WORK |
| A SECURITY OF THE STATE OF PERCENT AND IS CONSIDER | RED COVERED BY THE AFFIDAVIT. |
| Hang drill pipe at 3150' and pump | p in 40 sacks of cement. Calculated |
| C | · · · · · · · · · · · · · · · · · · · |
| Hang drill pipe at 680' and pump | in 255 sacks. Locate top of plug |
| at or above 596'. | |
| Plug top 10' of surface casing w | ith cement. Cut 7" off 5' below ground 10 |
| st ऐंग्लेमिटेंच्ये (date) (ne | t oil) (gravity) (cut) |
| <u>(ano)</u> | |
| 19 | OREGON NATURAL GAS DEVELOPMENT CORPORA |
| | Company or operator |
| en a soliturest | By N. 2 Meron |
| | Position Engineer, W. S. McBurine |
| | Send communications regarding well to |
| | Name Charles Stinson |
| | Name Undired Stinson |

Address 123 NW Flanders Street Portland, OR

97209

THE PRESENT OF GEOLOGY AND MINERAL INDUSTRIES

Director