PLUGGING RECORD

B12 X243

The owner or operator of any oil or gas well or stratigraphic hole shall file this form with the Director of the State of Oregon Department of Geology and Mineral Industries setting forth in detail the method used in plugging such well. The form must be filed within twenty (20) days after plugging for oil and gas wells, or within sixty (60) days for stratigraphic holes. Rule L of rules and regulations adopted pursuant to ORS 520, 095 (1) (13) (Chapter 667 OL 1953) Field Pittsburg Operator REICHHOLD ENERGY CORPORATION Clark & Wilson County Columbia ADDRESS ALL CORRESPONDENCE CONCERNING THIS FORM TO: Street 1410 S.W. Marlow Avenue Portland, Oregon__ Sec. 20 T. Investment Management 21-20 Well No. September 22, 19 83. Date well was plugged Was the well filled with mud laden fluid, according to regulations of the Board of the State of Oregon Department of Geology and Mineral Industries? Yes Mineral Industries? If so, show all shoulders left How was the mud applied? pumped yes Were plugs used? for casing, depth of each, and size of casing, size and kind of plugs used, and depths placed. Also amount of cement and rock. Use additional sheets if necessary. 8 5/8" casing set at 477' Bottom plug set from 1380' - 950' with 158 sks. class "G" cement Top plug set from 700'-377' with 120 sks. class "G" cement Was notice given, before plugging, to all available adjoining lease and land owners? REICHHOLD ENERGY CORPORATION AFFIDAVIT State of Oregon County of Columbia Todd Thomas , being duly sworn, say that I have knowledge of the facts stated herein, that they are true and correct, and that I am authorized to make this report. 26th day of September Subscribed and swom to before me this Notary public in and for said State My commission expires 8-10-85