## STATE OF OREGON D' MENT OF GEOLOGY AND MINERAL IND RIES 1069 State Office Building Portland 1, Oregon

## PLUGGING RECORD

The owner or operator of any oil or gas well or stratigraphic hole shall file this form with the Director of the State of Oregon Department of Geology and Mineral Industries setting forth in detail the method used in plugging such well. The form must be filed within twenty (20) days after plugging for oil and gas wells, or within sixty (60) days for stratigraphic holes.

Rule L of rules and regulations adopted pursuant to ORS 520.095 (1) (13)	(Chapter 667 OL 1953)
Operator Roderick A. Stamey Field	George B. Russell, Wildcat
Pool	
County_	Malheur
ADDRESS ALL CORRESPONDENCE CONCERNING THIS FORM TO:	Roderick A. Stamey
Street 311 Rusk Building City Houst	on ?, State Texas
Lease Name George B. Russell Well No. 1	Sec. 14 T. 19S R. 11 E
Date well was plugged September 17, 1954.	
Was the well filled with mud laden fluid, according to regulations of the Mineral Industries? Yes	Board of the State of Oregon Department of Geology and
How was the mud applied? *	ed? Yes # If so, show all shoulders left
for casing, depth of each, and size of casing, size and kind of plugs used,	and depths placed. Also amount of cement and rock.
Use additional sheets if necessary.	
* Freshly ground Bentonite was mixed with hole from approximately 3800 ft. to 400	the drill mud and numbed into
# Cement plug placed from 400 ft. to 187 at the request of the land owner, was lat the surface was omitted in order that so desired, make a water well. Especial cement plug upward to the surface. Approximately ap	eft in place and cement plug t the land owner might, if he
Poden	els (Sperator)
AFFIDAVIT	
State of Texas	
County of Harris	
Roderick A. Stamey	, being duly sworn, say that I have knowledge of
the facts stated herein, that they are true and correct, and that I am auth	
Subscribed and sworn to before me this 26 day of	June 19 58
Notary public in and for Harr	is County, Texas

June 1, 1959

My commission expires\_