DEFAUTHER OF GEOLOGY AND MINERAL INDUSTRIES

1069 to a Office Emilding Portland 1 region

PLUGGING RECORD

The owner or operator of any oil or gas well or stratigraphic hole shall file this form with the Director of the State of Oregon Department of Geology and Mineral Industries setting forth in detail the method used in plugging such well. The form must be filed within twenty (20) days after plugging for oil and gas wells, or within sixty (60) days for stratigraphic holes. Rule L of rules and regulations adopted pursuant to CRS 520, 095 (1) (13) (Chapter 667 OL 1953) Operator Reichhold Energy Corporation Mist Field Clark and Wilson Pool Columbia County ADDRESS ALL CORRESPONDENCE CONCERNING THIS FORM TO. City Portland Sucet 1410 S.W. Marlow Avenue 5W ___Well No. 11-5 ____ Sec. ___ 5 ___ T. ___ Wilson Lease Name October 12 1983. Date well was plugged Was the well filled with mud laden fluid, according to regulations of the Board of the State of Oregon Department of Geology and Mineral Industries? yes If so, show all shoulders left pumped Were plugs used? yes How was the mud applied? for casing, depth of each, and size of casing, size and kind of plugs used, and depths placed. Also amount of cement and rock. Use additional sheets if necessary. 8 5/8" casing set at 486'. Cemented with 215 sxs class "G" cement Bottom plug set from 1518' - 818' with 206 sxs class "G" cement Top plug set from 587' - 346' with 95 sxs class "G" cement Was notice given, before plugging, to all available adjoining lease and land owners? Yes Reichhold Energy Corporation (Operator) AFFIDAVIT Oregon State of Columbia County of ____, being duly sworn, say that I have knowledge of the facts stated herein, that they are true and correct, and that I am authorized to make this report. Subscribed and swom to before me this 21st day of October said State Notary public in and for ____ My commission expires 10-8-85