

Bunker Hill Elementary School

Coos Bay SD 9

Coos_sch02A

Building Type	County	
School	Coos	
Street		
62858 Hwy 101 S		
City	State	Zip
Coos Bay	OR	97420
Latitude	Longitude	
43.35331	124.20051	
Tracking Code	Inspection Date	
RVS in 2006	8/14/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Bunker Hill Elementary School

Final RVS Score

Final Type	Final Score
W2	0.5

FEMA-154 Collapse Potential


High (>10%)



OregonGeology

Bunker Hill Elementary School

Coos_sch02A

Enrollment 315	Year Built (Field Verified) 1955	Year Built (Alt. Source) 1955	Est. Decade Built 1950
Total Area (square ft) 25224	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		Steps in Elevation View: Single Change	
Torsion: Building Shape		None	
Non-Parallel System		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NE Plan Irregularity Secondary		E Other	Walkway is settling towards HWY 101 which is at a lower elevation.
			
S Plan Irregularity Primary			
			
SW Vertical Irregularity Primary			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries