

Riley Creek Elementary School

Central Curry SD 1

Curr_sch10A

Building Type	County
School	Curry
Street	
94350 Sixth St.	
City	State Zip
Gold Beach	OR 97444
Latitude	Longitude
42.40991	124.41408
Tracking Code	Inspection Date
RVS in 2006	8/4/2006



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Riley Creek Elementary School

Final RVS Score

Final Type	Final Score
W2	0.5

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Riley Creek Elementary School

Curr_sch10A

Enrollment 420	Year Built (Field Verified) 1957	Year Built (Alt. Source) 1950	Est. Decade Built 1950
Total Area (square ft) 64916	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes	
Out of Plane Lateral-Force-Resistance Elements		None	
Large Diaphragm or Central Opening		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
W Other This would be the fourth plan irregularity, Non-Parallel System.		W Plan Irregularity Primary	
		W Plan Irregularity Secondary	
		E Plan Irregularity Tertiary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries