

# Lakeview Fire Dept

City of Lakeview

Lake\_fir02A

Building Type	County
EOC-Public Safety Answering P	Lake
Street	
245 North F Street	
City	State Zip
Lakeview	OR 97630
Latitude	Longitude
42.19166	120.34636
Tracking Code	Inspection Date
RVS in 2006	6/27/2006



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Lakeview Fire Dept

## Final RVS Score

Final Type	Final Score
RM1	-0.1

## FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

# Lakeview Fire Dept

Lake\_fir02A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1984	1984	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	Yes
Plan Irregularities		Vertical Irregularities	
Lateral-Force-Resistance in One Direction Only		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Reentrant Corners: L Shaped (Adjacent Build/Entity)		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
N	Primary Structural Type	E	Plan Irregularity Primary



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
 Oregon Department of Geology and Mineral Industries