

Lakeview Senior High School

Lake County SD 7

Lake_sch05A

Building Type	County
School	Lake
Street	
906 S 3rd St	
City	State Zip
Lakeview	OR 97630
Latitude	Longitude
42.18633	120.35017
Tracking Code	Inspection Date
RVS in 2006	6/28/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	0	0	0	0	0	-1.8	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Lakeview Senior High School

Final RVS Score

Final Type	Final Score
W2	0

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Lakeview Senior High School

Lake_sch05A

Enrollment 305	Year Built (Field Verified) 1962	Year Built (Alt. Source) 1962	Est. Decade Built 1960
Total Area (square ft) 68881	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Large Diaphragm or Central Opening		Steps in Elevation View: Single Change	
Out of Plane Lateral-Force-Resistance Elements		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Reentrant Corners: L Shaped (Adjacent Build/Entity)		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
S	Elevation View	S	Elevation View
			
N	Elevation View	N	Vertical Irregularity Primary



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Lakeview Senior High School

Lake County SD 7

Lake_sch05B

Building Type	County
School	Lake
Street	
906 S 3rd St	
City	State Zip
Lakeview	OR 97630
Latitude	Longitude
42.18682	120.35031
Tracking Code	Inspection Date
RVS in 2006	6/28/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	0	-1.6	-0.5
Secondary	C2	3.6	-2	-0.5	0	0	0	0	-1.6	-0.5
Tertiary		0	0	0	0	0	0	0	0	0

Lakeview Senior High School

Final RVS Score

Final Type	Final Score
RM1	-0.5

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Lakeview Senior High School

Lake_sch05B

Enrollment 305	Year Built (Field Verified) 1962	Year Built (Alt. Source) 1962	Est. Decade Built 1960
Total Area (square ft) 68881	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners:L shaped (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change Steps in Elevation View: Single Change (Adjacent Building/Entity) None	
Falling Hazards Other: Ornamental Hazard Over Exit None None		Poor Conditions None None None	
 E Vertical Irregularity Primary		 N Elevation View	

Lakeview Senior High School

Lake County SD 7

Lake_sch05C

Building Type	County
School	Lake
Street	
906 S 3rd St	
City	State Zip
Lakeview	OR 97630
Latitude	Longitude
42.1861	120.34942
Tracking Code	Inspection Date
RVS in 2006	6/28/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	3.4	-1.5	-0.5	-0.4	0	0	-0.8	0	0.2
Secondary	W2	4.8	-3	-0.5	-0.2	0	0	-1.2	0	-0.1
Tertiary		0	0	0	0	0	0	0	0	0

Lakeview Senior High School

Final RVS Score

Final Type	Final Score
W2	-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Lakeview Senior High School

Lake_sch05C

Enrollment 305	Year Built (Field Verified) 1962	Year Built (Alt. Source) 1962	Est. Decade Built 1930
Total Area (square ft) 68881	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: L Shaped None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards Unreinforced Chimneys Other: Brick Veneer None		Poor Conditions Cracks None None	
			
E Elevation View	N Elevation View	W General Site	
			
W Falling Hazard	W Primary Structural Type		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries